

# 辉陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

05/09/2024

Owner: AUTOGALLERY @ JDM

## ESTIMATE TO REPAIR TOYOTA SIENTA HYBRID - SNN6531E

|      |                                                     |        |             |   |
|------|-----------------------------------------------------|--------|-------------|---|
| 1pc  | rear tailgate                                       | Rt     | \$ 1,358.50 | ✓ |
| 1pc  | rear tailgate "HYBRID" emblem                       | ma     | \$ 89.50    | ✓ |
| 1pc  | rear tailgate "TOYOTA" emblem                       | ma     | \$ 75.20    | X |
| 1pc  | rear tailgate outer garnish                         | su     | \$ 485.20   | X |
| 1pc  | rear tailgate inner lock                            | re     | \$ 425.50   | X |
| 1pc  | rear tailgate inner rubber 290                      | nd/dit | \$ 381.90   | ✓ |
| 1pc  | rear tailgate inner cardboard                       | pu     | \$ 281.50   | X |
| 1pc  | rear tailgate inner handle                          | su     | \$ 121.50   | X |
| 1pc  | rear tailgate windscreen moulding                   | ma     | \$ 181.50   | ✓ |
| 1pc  | rear LH taillamp 581.50                             | su     | \$ 685.20   | ✓ |
| 1pc  | rear bumper 585                                     | bu     | \$ 1,125.20 | ✓ |
| 2pcs | rear bumper side reflector @\$132.10 95             | ma     | \$ 264.20   | ✓ |
| 8pcs | rear bumper clip @\$5.00                            | ma     | \$ 40.00    | ✓ |
| 1pc  | rear bumper towing cover                            | pu     | \$ 85.20    | X |
| 2pcs | rear bumper centre parking sensor @\$258.50         | nd/dit | \$ 517.00   | ✓ |
| 4pcs | rear bumper centre parking sensor base @\$85.50 665 | ma     | \$ 342.00   | ✓ |
| 1pc  | rear end panel outer                                | su     | \$ 564.20   | ✓ |
| 1pc  | rear end panel outer sensor                         | su     | \$ 281.50   | X |
| 1pc  | rear end panel inner                                | re     | \$ 781.45   | X |
| 1pc  | rear end panel inner garnish 250                    | nd/dit | \$ 371.85   | ✓ |

\$ 8,458.10

less 25%

\$ 2,114.53

\$ 6,343.58

1set rear number plate & casing

s.nett \$ 50.00 X

remove & refix rear windscreen glass

\$ 150.00

sealant

\$ 80.00

tuffkote

\$ 80.00

wiring

\$ 80.00

spray painting

\$ 1,000.00

labour charges

\$ 1,000.00

Total

\$ 8,783.58

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

120L  
405L  
60L  
20L  
660L  
600L

ECICS  
LKK  
09/09/24  
(mon)

Not withain

61 Day @ 3900h

Penalty After Pain

5 days