

Not Authorized
11 Sep 82300p

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5965S

AAD2407-072

09 SEP 2024

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD5965S

JTDKB3FU703075517

200303878K

TOYOTA

PRIUS

17/7/2024

SNA6988P/

1/11/2018

PART		LIST	
1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	1,641.36 X
1	PANEL SUB-ASSY, REAR DOOR, LH	\$	1,634.33
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, LH	\$	243.81 X
1	HANDLE ASSY, REAR DOOR OUTSIDE, LH	\$	123.06 X
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, LH	\$	369.60 X
1	HINGE ASSY, REAR DOOR, LOWER LH	\$	109.62 X
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	124.74 X
1	TAPE, BLACK OUT, NO.1 REAR LH	\$	27.62
1	TAPE, BLACK OUT, NO.2 REAR LH	\$	44.00
1	TAPE, BLACK OUT, NO.3 REAR LH	\$	19.43
1	COVER, REAR COMBINATION LAMP, LH	\$	81.48
1	LENS & BODY, REAR COMBINATION LAMP, LH	\$	559.13
1	LENS AND BODY, REAR LAMP, LH	\$	634.73
1	COVER, REAR BUMPER	\$	558.39
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	419.90
1	GUARD, REAR BUMPER, CENTER	\$	726.92
1	FILLER, REAR BUMPER EXTENSION, LH	\$	155.72
1	SEAL, REAR BUMPER SIDE, LH	\$	111.41
1	RETAINER, REAR BUMPER SIDE, LH	\$	147.11
1	PANEL SUB-ASSY, QUARTER, LH	\$	1,099.46
1	LINER, REAR WHEEL HOUSE, LH	\$	176.09
1	MOULDING ASSY, BODY ROCKER PANEL, LH	\$	624.54
TOTAL		\$	9,632.41
25%		\$	2,408.10
		\$	7,224.30

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5965S**AAD2407-072****Special Nett**

1SET DOOR TRIM CLIP	\$	na	70.00	X
1SET DOOR WEATHERSTRIP CLIP	\$	na	65.00	X
1 DOOR STICKER TEL NO.	\$	na	100.00	60/na
1 REAR BUMPER CLIP	\$	na	65.00	X
1SET CLIP, ROCKER PANEL MOULDING	\$	na	65.00	X
1SET FENDER CLIP	\$	na	130.00	X
1 FENDER LINER CLIP	\$	na	65.00	X
TOTAL	\$		560.00	
TOTAL PARTS	\$		2,300.00	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	30/
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	60/
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	500/
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	880/
To transfer of tire, rim and on wheel balancing.	\$	na	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00	20/
To check steering geometry and computer wheel alignment	\$	4	220.00 X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	4	170.00 X
TOTAL	\$	4,550.00	

KKK Auto Straddlement and notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3 days