


PHOTOGRAPHS FOR VEHICLE NO. : YR 2144P




PHOTOGRAPHS FOR VEHICLE NO. : YR 2144P




PHOTOGRAPHS FOR VEHICLE NO. : YR 2144P




PHOTOGRAPHS FOR VEHICLE NO. : YR 2144P



PHOTOGRAPHS FOR VEHICLE NO. : YR 2144P




PHOTOGRAPHS FOR VEHICLE NO. : YR 2144P






PHOTOGRAPHS FOR VEHICLE NO. : YR 2144P



PHOTOGRAPHS FOR VEHICLE NO. : YR 2144P



PHOTOGRAPHS FOR VEHICLE NO. : YR 2144P



PHOTOGRAPHS FOR VEHICLE NO. : YR 2144P







LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 11 of 16)



PHOTOGRAPHS FOR VEHICLE NO. : YR 2144P




PHOTOGRAPHS FOR VEHICLE NO. : YR 2144P



PHOTOGRAPHS FOR VEHICLE NO. : YR 2144P



PHOTOGRAPHS FOR VEHICLE NO. : YR 2144P



PHOTOGRAPHS FOR VEHICLE NO. : YR 2144P



PHOTOGRAPHS FOR VEHICLE NO. : YR 2144P

