



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNJ 523P

Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	MOULDING RR PAD (N)	SCRATCHED	\$280.30	\$280.30
1	MOULDING FR PAD (N)	NOT NECESSARY	\$497.20	\$0.00
1	DOOR-FRONT RH (N)	TO REPAIR SEE LABOUR	\$1,216.20	\$0.00
1	TAPE-FR DOOR,RH (N)	NOT NECESSARY	\$23.40	\$0.00
1	TAPE-FR DOOR,RH (N)	NOT NECESSARY	\$31.20	\$0.00
1	DOOR-REAR RH (N)	TO REPAIR SEE LABOUR	\$970.00	\$0.00
1	TAPE-RR DOOR, RH (N)	NOT NECESSARY	\$21.70	\$0.00
1	TAPE-RR DOOR, RH (N)	NOT NECESSARY	\$25.20	\$0.00
1	TAPE-RR DOOR IN (N)	NOT NECESSARY	\$16.10	\$0.00
1	OVER FENDER-REA (N)	SCRATCHED	\$419.80	\$419.80
4	CLIP TRIM @\$3.60 (N)	NOT NECESSARY	\$14.40	\$0.00
2	CLIP @\$16.50 (N)	NOT NECESSARY	\$33.00	\$0.00
2	CLIP @\$3.00 (N)	NOT NECESSARY	\$6.00	\$0.00
1	EMBLEM, SIDE FR (N) (ADDITIONAL)	NECESSARY	\$105.00	\$105.00
	<b>LESS 20.00%</b>		(\$731.90)	(\$161.02)
			\$2,927.60	\$644.08
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	MUDGUARD SILL (SN)	NOT NECESSARY	\$130.60	\$0.00
1	SUNDRIES (SN)	NECESSARY	\$30.00	\$20.00
			\$160.60	\$20.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	CONDUCT CONSULT,RESET & PROGRAMMING		\$240.00	\$240.00
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	NOT NECESSARY	\$120.00	\$0.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY 2X AREA PANEL	NOT NECESSARY	\$200.00	\$0.00
	TRANSFER MECHANISM PART FOR RH SIDE FR/RR DOOR \$80 X 2	NOT NECESSARY	\$160.00	\$0.00
	REPAIR RH SILL PANEL/RR FENDER RENEW RH SIDE FR/RR DOOR. INCLUSIVE OF THE REPAIR OF DOOR-FRONT RH AND DOOR-REAR RH		\$1,505.00	\$1,075.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	S/PAINT RH SIDE FR/RR DOOR/SILL PANEL/RR FENDER		\$1,520.00	\$1,140.00
			\$3,745.00	\$2,455.00
GRAND TOTAL			\$6,833.20	\$3,119.08
	RECOMMENDED COST OF REPAIRS			\$3,119.08
Report Ref No: CS/FCI24090125/Rnp3m4				

**MRB**

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.