

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SNJ523P

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED	SURVEYOR'S
			CHARGES	RECOMMENDATION
1	CRP	CONDUCT CONSULT, RESET & PROGRAMMING	240.00	
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	Xnn
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY 2X AREA PANEL	200.00	Xnn
4	ZZ/001	TRANSFER MECHANISM PART FOR RH SIDE FR/RR DOOR \$80 X 2	160.00	Xnn
5	ZZ/002	REPAIR RH SILL PANEL/RR FENDER RENEW RH SIDE FR/RR DOOR	1505.00	1075
6	ZZ/003	S/PAINT RH SIDE FR/RR DOOR/SILL PANEL/RR FENDER	1520.00	1140
TOTAL LABOUR CHARGES			3745.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SNJ523P

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 MOULDING RR PAD <i>scd /</i>	82870-5RY0B	280.30 <i>/</i>		
2 MOULDING FR PAD <i>X n n</i>	80870-5RY0B	497.20		
3 MUDGUARD SILL <i>X n n</i>	76850-5RY0A			130.60
4 DOOR-FRONT RH <i>repl</i>	H010M-5RYMA	1216.20		
5 TAPE-FR DOOR, RH <i>X n n</i>	80818-5RY0A	23.40		
6 TAPE-FR DOOR, RH <i>X n n</i>	80816-5RY0A	31.20		
7 DOOR-REAR RH <i>repl</i>	H210M-5RYMA	970.00		
8 TAPE-RR DOOR, RH <i>X n n</i>	82818-5RY1A	21.70		
9 TAPE-RR DOOR, RH <i>X n n</i>	82816-5RY0A	25.20		
10 TAPE-RR DOOR IN <i>X n n</i>	82814-5RY0A	16.10		
11 OVER FENDER-REA <i>scd /</i>	93828-5RY0A	419.80 <i>/</i>		
12 CLIP TRIM(\$3.6X4) <i>X n n</i>	76882-JG10A	14.40		
13 CLIP(\$16.5X2) <i>X n n</i>	01553-1HA0A	33.00		
14 CLIP(\$3X2) <i>X n n</i>	01553-09241	6.00		
15 SUNDRIES <i>nec</i>	NPN			<i>20 30.00 /</i>
SUB TOTAL		3554.50	0.00	160.60
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		710.90	0.00	0.00
GRAND TOTAL		2843.60	0.00	160.60
OVERALL TOTAL		3004.20		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SNJ523P

TOTAL LABOUR CHARGES	3745.00
TOTAL SPARE PARTS CHARGES	3004.20
GRAND TOTAL	6749.20 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME

SURVEYED DATE

AUTHORIZED DATE

EXCESS CLAUSE

LIABILITY

REMARKS

Rasul - Hp 90010068
12/11/24 4-5 days
Pay 68 per cent

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.

13-Nov-2024

INS/IC/ZHR/0268/2024

MS FIRST CAPITAL INSURANCE LTD
30 ROBINSON ROAD
#16-01 CITY HOUSE
Singapore 068877

Attn : Motor Claim Manager
Claim Dept

Dear Sir

SUPPLEMENTARY CLAIM

REGN. NO. : SNJ523P
POLCY NO. : TP-SHC3264A

Further to our claim we are submitting a supplementary claim for the below mentioned items which were found damaged during the course of repairs.

	<u>Replacement of Damaged Items</u>	
1	EMBLEM, SIDE FR <i>me /</i>	\$105.00 NETT

TOTAL \$ 105.00

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully
TAN CHONG MOTOR SALES PTE LTD

M.ZUHRI
Insurance Claim Dept

Cc: Surveyor