



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24060149/Uvh3
(BUDGET DIRECT INSURANCE)	Date:	23/07/2024
190 CLEMENCEAU AVENUE #03-01		
SINGAPORE SHOPPING CENTRE SINGAPORE 239924	Code:	AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKV 5081L	Veh. Inspected	SFV 5688X
Policy No.	P10703540R02	Coverage	0
Claim No.	C10029995/HY	Excess	\$0.00
Assign From	MICHAEL	Assign Date	19/06/2024

2. Vehicle Details

Make & Model	SUZUKI SWIFT SPORT (M)	C.C	1586
Engine No.	M16A1656961	Year of Reg.	20/04/2012
Chassis No.	JSAFZC32S00100727	Colour	GREY
Odometer	126694 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/55R15	YOKOHAMA	6
L/H Front Tyre	195/55R15	YOKOHAMA	6
R/H Rear Tyre	195/55R15	YOKOHAMA	6
L/H Rear Tyre	195/55R15	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/06/2024	Inspection Date	19/06/2024
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days