

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24090129/UMA3Q2**Date:** 14/01/2025**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210030824
Claimant Vehicle No : SLM9331A **Insured Vehicle No :** SFX2096M
 Date of Loss: 06/09/2024 Nature of Claim: TP Claim No: 3623377716SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM9331A**
 Make & Model: NISSAN QASHQAI, 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R (A) Engine No: MR20457030W
 Reg. Date: 18/04/2017 (Man. Year: 2017) Chassis No: SJNFBAJ11U1941033
 Colour: Silver Odometer: 217269 km
 Engine Capacity: 1997 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R19 Rear Tyre Size: 225/45 R19
 Front Left Side: Yokohama 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,593.90	1,095.23	2,498.67	69.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,215.00	800.00	1,415.00	63.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,808.90	1,895.23	3,913.67	67.37
Approved Total (Overridden) (S\$)		1,500.00		
(S\$)	5,808.90	1,500.00	4,308.90	74.18
+ GST 9.00/9.00% (S\$)	522.80	135.00	387.80	74.18
Nett Amount (S\$)	6,331.70	1,635.00	4,696.70	74.18
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		1,937.18		
Global Sum Settlement (S\$)		1,900.00		

INSPECTION

Date of Assignment: 20/09/2024
 Date Inspected: 20/09/2024 Inspected At: Specialists Motor Pte Ltd (HQ)
 Blk 3018A Ubi Road 1, #01-24/25/26
 Singapore 408711
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPR FASCIA	Cut / Deformed	975.80 F	*975.80 FL
2	1		*SET REAR BUMPR CLIPS	Necessary	18.90 F	*18.90 FL
3	2		*REAR BUMPER SIDE RETAINER L&R	Not Necessary	86.60 F	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Serviceable	746.20 F	*- FL
5	1		*REAR BUMPER SPONGE	Not Necessary	173.40 F	*- FL
6	2		*REAR BUMPER BRACKET L&R	Not Necessary	314.20 F	*- FL
7	1		*REAR END PANEL	Repair	591.60 F	*- FL
8	1		*REAR BOOT COVER EMBLEM (LOGO)	Not Necessary	72.20 F	*- FL
9	1		*REAR BOOT COVER EMBLEM (QASHQAI)	Not Necessary	105.00 F	*- FL
10	1		*SET REAR BUMPER SENSOR	Cut / Damaged	380.00 FS	*200.00 FS
11	1		*SET REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
12	1		*SET REAR END PANEL SEALER	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,593.90	1,194.70
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	99.47
Total Parts (\$)	3,593.90	1,095.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OUT RENEW KNOCKING & WELDING REAR END PANEL ,REMOVE & INSTALL ALL DAMAGE PARTS,STRAIGHTEN & REALIGN BODY	New	1,080.00	350.00
2	TUFF KOTE ON DAMAGE PARTS	New	40.00	0.00
3	SPRAY PAINTING ON DAMAGE PARTS	New	980.00	400.00
4	REMOVE & REPLACED REAR BUMPER SENSOR	New	80.00	30.00
5	CHECK ALL LIGHTING AFTER REPAIRS	New	35.00	20.00
Gross Labour Cost (\$\$)			2,215.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >