

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLM9331A/2409139

06th September 2024

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Date of Accident : 06TH September 2024
Location : PIE Exit to Kim Keat Link
Third Party Claim Vehicle No : SFX 2096 M
Repair Cost For Vehicle No : SLM 9331 A Nissan Qashqai

Estimated Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear bumper fascia cur/de	1	975.80	\$ 975.80 ✓
2	Rear bumper clips de	1set	18.90	\$ 18.90 ✓
3	Rear bumper side retainer L&r an	2	43.30	\$ 86.60 x
4	Rear bumper reinforcement su	1	746.20	\$ 746.20 q
5	Rear bumper sponge an	1	173.40	\$ 173.40 x
6	Rear bumper bracket L&R an	2	157.10	\$ 314.20 x
7	Rear end panel n	1	591.60	\$ 591.60 x
8	Rear boot cover emblem (logo) an	1	72.20	\$ 72.20 x
9	Rear boot cover emblem (Qashqai) an	1	105.00	\$ 105.00 x
10	Rear bumper sensor (s/nett) cur/de	1set	380.00	\$ 380.00 2005/10
11	Rear number plate (s/nett) an	1set	50.00	\$ 50.00 x
12	Rear end panel sealer (s/net) an	1set	80.00	\$ 80.00 x
				\$ 3,593.90

102

not Aulboul
her
means
20/8/24
L/S \$1500
Telapht. After my
3 days.

Nett item

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLM9331A/2409139

06th September 2024

Balance b/f \$ 3,593.90

Labour Charges :-

Amounts

Cut out, renew, knocking & welding rear end panel, remove & install all damage parts, straighten & re-align body	\$ 1,080.00	350
Tuff-kote on damage parts	\$ 40.00	X
Spray painting on damage parts	\$ 980.00	400
Remove & ^{replace} rear bumper sensor	\$ 80.00	30
Check all lighting after repairs	\$ 35.00	20

Labour Charge \$ 2,215.00

Total Amount \$ 5,808.90

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 994.7
102
895.23
200
800
1895.23
202
1516.