

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090130/RUA3Q2
Date: 07/01/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002582_01
Claimant Vehicle No : SGB17J Insured Vehicle No : SLQ3924H
Date of Loss: 03/09/2024 Nature of Claim: TP Claim No: MFL2024D0010471

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGB17J
Make & Model: BMW IX, XDRIVE40 SPORTS LED PGR (A) Engine No: HIDDEN
Reg. Date: 02/08/2024 (Man. Year: 2023) Chassis No: WBY12CF040CP32409
Colour: White Odometer: 397 km
Engine Capacity: 0 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/50 R21 Rear Tyre Size: 255/50 R21
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	50.00	20.00	30.00	60.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,360.00	4,025.00	2,335.00	36.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,410.00	4,045.00	2,365.00	36.90
+ GST 9.00/9.00% (S\$)	576.90	364.05	212.85	36.90
Nett Amount (S\$)	6,986.90	4,409.05	2,577.85	36.90
+ Loss of Use (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		5,036.30		

INSPECTION

Date of Assignment: 10/09/2024
Date Inspected: 10/09/2024 Inspected At: Eurokars Auto Pte Ltd
11 Kung Chong Road
Singapore 159147
Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Nov 2024)
Parts:	143	BMW IX XDRIVE40 SPORTS LED PGR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGB17J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
			F=Franchise part. S=SpcNett.			
				Total Parts (S\$)	50.00	20.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE /REPLACE DAMAGED BODYPARTS TO REPAIR FRONT BUMPER ,FRONT LH FENDER AND ALL AREAS AFFECTED BY THE ACCIDENT	New	2,550.00	1,275.00
2	TO RESPRAY FRONT BUMPER & FRONT LH FENDER	New	2,000.00	1,440.00
3	TO REPAIR AND RESPRAY FRONT LH RIM	New	250.00	250.00
4	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	560.00	560.00
5	TO ISOLATE THE EV BATTERY DURING THE REPAIRS INCLUDING CHARGING OF BATTERY	New	250.00	0.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	500.00	350.00
Gross Labour Cost (\$\$)			6,360.00	4,025.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >