

MY CAR CONSULTANT PTE LTD

Reg no.201605878Z

Address: NO:6 JALAN LAM HUAT, CARROS CENTRE #05-68 5737869

HP: 98888885/97816380

Estimation

Date:

9/9/2024

Vehicle:

SNJ1053Y

Make / Model:

TOYOTA CAMRY

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER / <i>OD</i>	1	\$ 1,025.00	\$ 1,025.00
2	REAR BUMPER LOWER LID / <i>cut</i>	1	\$ 820.50	\$ 820.50
3	REAR BUMPER SPONGE SET <i>X</i>	1	\$ 128.00	\$ 128.00
4	REAR BUMPER REINFORCEMENT <i>X</i>	1	\$ 598.20	\$ 598.20
5	REAR BUMPER REFLECTOR LH / <i>cut</i>	1	\$ 78.00	\$ 78.00
6	REAR BUMPER SIDE GARNISH LH <i>X</i>	1	\$ 82.00	\$ 82.00
7	REAR BUMPER SIDE RETAINER / <i>BR</i>	2	\$ 148.00	\$ 296.00
9	TAILAMP LH / <i>BR</i>	1	\$ 812.00	\$ 812.00
10	TAILAMP GARNISH LH <i>X</i>	1	\$ 85.00	\$ 85.00
11	REAR FENDER LH <i>X R</i>	1	\$ 1,025.00	\$ 1,025.00
12	REAR FENDER INNER TRIM LH <i>X</i>	1	\$ 812.00	\$ 812.00
13	REAR FENDER COWLING LH <i>X</i>	1	\$ 212.00	\$ 212.00
14	REAR END PANEL <i>X R</i>	1	\$ 698.00	\$ 698.00
				\$ 6,671.70
				Less 25%
				\$ 1,667.93
				Total
				\$ 5,003.78
S/Nett items:				
1	REVERSE SENSOR / <i>shiled</i>	1	\$ 250.00	\$ 250.00
2	REAR BUMPER CLIP SET / <i>nk</i>	1	\$ 80.00	\$ 80.00
3	REAR FENDER INNER TRIM CLIPS SET <i>X</i>	1	\$ 50.00	\$ 50.00
4	END PANEL SEALANT <i>X</i>	1	\$ 50.00	\$ 50.00
				\$ 430.00
Labour to:				
1	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,000.00	\$ 1,000.00
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,200.00	\$ 1,200.00
3	REMOVE AND REFIT REAR SEAT, INNER TRIM SPEAKER	1	\$ 200.00	\$ 200.00
4	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
5	TO REMOVE AND REFIT REVERSE SENSOR / CAMERA	1	\$ 150.00	\$ 150.00
6	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
				\$ 2,830.00
<i>Steve (LKK)</i> <i>9/9/24, 11.00am</i> <i>W 12</i> <i>L/S</i> <i>By AL ry</i> <i>3 days</i>		Parts Replacement Amount		\$ 5,433.78
		Total Amount for Labour		\$ 2,830.00
		Total Amount		\$ 8,263.78

570 /
412 /
/
148 /
/
200
30
400
300
X
30
30
20