

TICK HAI MOTOR & WELDING SERVICES
1 KAKI BUKIT AVE 6 #01-54 SINGAPORE 417883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 48992400W

Vehicle Number: SLB8129H

Vehicle Model : Honda Jazz 1.5 VTIR CVT ABS D/Airbag 2WD

Chassis : JHMGK5850GX202572

Year of Manufacture : 2016

NOT Authorized
 2nd month
 10/9/24
 2/5 + 3000/
 telephone
 4 hrs.

S/N.	Item Description	Amount (\$)
1	Rear Boot Tailgate 822.40 20/201	\$ 1,236.00
2	Rear Boot Inner Lock 80	\$ 354.85
3	Rear Boot Catch 11	\$ 85.01
4	Rear Boot Trimboard 11	\$ 393.49
5	Rear Boot Trimboard Clip x 1 set 11	\$ 30.00
6	"JAZZ" Emblem 30 111	\$ 75.05
7	"RS" Emblem 45 111	\$ 69.34
8	Rear Boot Weatherstrip 110.80 111	\$ 240.16
9	Taillamp (RH) 285.40 111	\$ 525.75
10	Rear Bumper 566.20 20/201	\$ 1,318.45
11	Rear Bumper Side Retainer (RH) 11	\$ 47.34
12	Rear Bumper Clip x 1 set 111	\$ 30.00
13	Rear Bumper Black Cover (RH) 111	\$ 66.30
14	End Panel 349.80 20	\$ 717.04
15	End Panel Top Garnish 108.60 111	\$ 263.40
16	Rear Windscreen Moulding x 1 set 98.50 111	\$ 279.01
Total :		\$ 5,731.19
Less 10% :		\$ 573.12
Amount :		\$ 5,158.07

S/N	Special Nett Item	Amount (\$)
1	Reverse Sensor x 2 pcs 80	\$ 240.00
2	End Panel Sealant 111	\$ 80.00
3	Windscreen Sealant 111	\$ 80.00
Amount :		\$ 400.00

Labour	Amount (\$)
To check rear electrical wiring system	\$ 80.00
To remove & reinstall reverse sensor	\$ 120.00
To remove & reinstall rear windscreen	\$ 150.00
To transfer rear boot components from old boot to new boot	\$ 200.00
To apply anti-rusting coating on new & affected panels	\$ 150.00
To remove & reinstall rear inner trims, garnishes etc to facilitate repair	\$ 250.00
To remove, replace above listed parts and panel beat accident affected parts	\$ 1,800.00
To spray painting on affected areas	\$ 1,500.00
Labour Total :	\$ 4,250.00
Total (Parts & Labour)	\$ 9,808.07

20

30

120

50

50

60

600

750

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts pending resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p- 2513

202

2010.40

70

168

37604

202

3008