

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/2124090133/4uh3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLB 8129H
at Workshop m/s Tick he's lpu
of _____
Insured: SDR 1248D
Policy No. _____
Claims No. IVS24/1702
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its
repair at the time of inspection.**

N/S	O/S
	A

Bal. or Market Value: 826k
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 4 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

732B
Vehicle: IN / OUT

Date: _____ Person Contacted: L7A014284

Veh No: SLB 8129H Yr Regn: 11/05/16
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or 4
Make: Hunda 15 c.c. 1498
Colour: Silver A/C: Insured / Std / NI / NA
Sp. Reading: 153417 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JHMAK 58506 * X 202572
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/50 R 16
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front 6 Rear 6
R/Bal. _____ mm R/Bal. _____ mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 04/09/24 D.O.I. 10/9/24
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear O/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>25/9/24</u>	<u>1/5 @ 3000 informed Robert (red 6808.07, 69%)</u>

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: 4

1)

☐

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

____ \$ + RS, ____ SI

Photos

Others

Report Format :

Lump Sum / I.B.I.: (\$ _____)

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 732B

Vehicle Details

Vehicle No.: SLB8129H

Vehicle to be Exported: No

Intended Deregistration Date: 10 Sep 2024

Vehicle Make: HONDA

Vehicle Model: JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD

Primary Colour: Silver

Manufacturing Year: 2016

Engine No.: L15B31021023

Chassis No.: JHMGK5850GX202572

Maximum Power Output: 96.0 kW (128 bhp)

Open Market Value: \$16,639.00

Original Registration Date: 11 May 2016

First Registration Date: 11 May 2016

Transfer Count: 1

Actual ARF Paid: \$11,639.00 5819

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 10 May 2026

PARF Rebate Amount: \$6,401.00

Intended COE Rebate Details

COE Expiry Date: 10 May 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$47,300.00

COE Rebate Amount: \$7,883.00

Total Rebate Amount: \$14,284.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 10 Sep 2024

OK



Home Used Cars-Listing

All Category

Filter

Search

Save Search



2016 X

18 Vehicles

Car Make

Car Model

Price Range

Depreciation

2016

Mileage

Honda Jazz 1.5A RS **\$23,500**

Instl. \$1,209 /mth

\$13,850 /yr

06-Jan-2016



114,000 km

3 Owners



Actual owner count only 2 due to family transfer. Full agent maintained the last 9 years! Reliable and great fuel efficiency! Very good condition! Interior like new. Immediate transfer. Cash deal welcomed. Letting go as new car is coming.

Posted 10-Sep-2024

☐ Compare

DIRECT OWNER

Honda Jazz 1.5A RS **\$27,000**

Instl. \$1,151 /mth

\$14,100 /yr

18-Mar-2016



116,350 km

1 Owner



Kah motor unit. Agent maintained. One owner. High specs 1.5 RS model red exterior with black leather seats interior. Low PARF value! Definitely good to go for another new 10 years of COE. Most popular Honda hatch back in the market. Attractive low-interest rate of 2.78%. Please call our sales consultant for more enquiries and viewing appointment. Otopac Motors Pte Ltd|Posted 10-Sep-2024

☐ Compare

PREMIUM AD

Honda Jazz 1.5A RS **\$28,800**

Instl. \$1,162 /mth

\$14,560 /yr

15-Apr-2016



136,000 km

2 Owners



2 owners only. Kah Motors unit Honda authorised dealer. Bank loan and in house loan available! Trade in welcome! Cheers! Posted 09-Sep-2024

☐ CompareHonda Jazz 1.5A **\$27,800**

Instl. \$1,121 /mth

\$13,930 /yr

15-Apr-2016



95,000 km

3 Owners



Very Good Condition! You will regret it if you missed it! Smooth and powerful! Small but spacious inside and reliable family car! Bank/full loan at lowest interest rate available! Free 1 year premium warranty! Free 1 time servicing! Free interior detailing and 3 step polishing! Welcome all kinds of trade in. Call us now to view Posted 07-Sep-2024

☐ Compare

Compare

TICK HAI MOTOR & WELDING SERVICES
1 KAKI BUKIT AVE 6 #01-54 SINGAPORE 417883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 48992400W

Vehicle Number: SLB8129H
 Vehicle Model : Honda Jazz 1.5 VTIR CVT ABS D/Airbag 2WD
 Chassis : JHMGK5850GX202572
 Year of Manufacture : 2016

not Authorized
 an
 mera's
 10/9/24
 d / 6 + 3000 /
 telephone. Attorney--
 4 by s.

S/N.	Item Description	Amount (\$)
1	Rear Boot Tailgate 822.40 20/2nt	\$ 1,236.00
2	Rear Boot Inner Lock 8u	\$ 354.85
3	Rear Boot Catch 11	\$ 85.01
4	Rear Boot Trimboard 11	\$ 393.49
5	Rear Boot Trimboard Clip x 1 set 11	\$ 30.00
6	"JAZZ" Emblem 30 111	\$ 75.05
7	"RS" Emblem 45 111	\$ 69.34
8	Rear Boot Weatherstrip 110.80 7w1	\$ 240.16
9	Taillamp (RH) 285.40 cu	\$ 525.75
10	Rear Bumper 566.20 20/2e	\$ 1,318.45
11	Rear Bumper Side Retainer (RH) 11	\$ 47.34
12	Rear Bumper Clip x 1 set 111	\$ 30.00
13	Rear Bumper Black Cover (RH) 117	\$ 66.30
14	End Panel 349.80 20	\$ 717.04
15	End Panel Top Garnish 108.60 1w1	\$ 263.40
16	Rear Windscreen Moulding x 1 set 98.50 111	\$ 279.01
	202 Total :	\$ 5,731.19
	Less 10% :	\$ 573.12
	Amount :	\$ 5,158.07

S/N	Special Nett Item	Amount (\$)
1	Reverse Sensor x 2 pcs 811	\$ 240.00
2	End Panel Sealant 111	\$ 80.00
3	Windscreen Sealant 111	\$ 80.00
	Amount :	\$ 400.00

Labour	Amount (\$)
To check rear electrical wiring system	\$ 80.00
To remove & reinstall reverse sensor	\$ 120.00
To remove & reinstall rear windscreen	\$ 150.00
To transfer rear boot components from old boot to new boot	\$ 200.00
To apply anti-rusting coating on new & affected panels	\$ 150.00
To remove & reinstall rear inner trims, garnishes etc to facilitate repair	\$ 250.00
To remove, replace above listed parts and panel beat accident affected parts	\$ 1,800.00
To spray painting on affected areas	\$ 1,500.00
Labour Total :	\$ 4,250.00
Total (Parts & Labour)	\$ 9,808.07

20
30
120
50
50
60
600
750

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, and a survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 2513
22
2010.40
70
162
37624
226
3028