

来發 ( 明 記 ) 摩 哆 有 限 公 司  
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

ESTIMATE

EST. No ..... EST0035673  
Ng Soo Yong

Page ..... 1 of 1  
Your ref. .... TP-SLG 2938C India  
Job No. .... 74695  
Our ref. .... 24.09.07  
Payment .....  
Date ..... 6/9/2024

Attn .....

Vehicle No .... SME 6706C  
Vehicle Model : Kia Cerato  
Accident on ... 5/9/2024

Not Authored  
Repair B4 painting  
81450.08 9 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Front fender RH	588.00	10.00	529.20
4.00	Pcs	Front fender inner shield clips RH	5.80	10.00	20.88
Labour & Misc:					
1.00		To repair front bumper and renew parts	450.00		450.00
1.00		To spray paint (include blend front door RH)	600.00		600.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub-Total

GST 9.00%

Total

1,600.08

144.01

SS

1,744.09

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

