

Date: 5-9-2024
 Vehicle No: SNG5671C
 Model: Tesla Model 3
 Chassis: LRW3F7FS2NC601751
 Reg.Year: 18.8.2022

NOT Authorized
Runway B4pain
4 days
4225-86

Third Party Insurer: AIG
 Third Party Veh No: SMR657G
 Date of Accident: 5/9/2024
 Estimator: Loong
 Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1	Bu	\$766.00
2	FRONT RH BUMPER RETAINER	1	na	\$1.86
3	FRONT RH BUMPER SIDE SUPPORT BRACKET	1	CM	\$12.14
4	FRONT RH BUMPER FOG LAMP COVER	1	na	\$6.54
5	FRONT PARKING SENSOR	1	Shut	\$163.55
6	FRONT BUMPER LOWER	1	na	\$186.91
7	FRONT BUMPER ENERGY ABSORBER	1	na	\$46.72
8	FRONT RH FENDER PANEL	1	Bu	\$448.60
9	FRONT RH FENDER LINER	1	CM	\$116.82
10	FRONT RH HEADLAMP	1	my CM	\$1,741.00
11	FRONT RH WHEEL RIM COVER	1	na	\$32.40
12	FRONT RH WHEEL RIM	1	na	\$505.00
13	FRONT RH KNUCKLE ARM	1	na	\$420.56
14	FRONT RH KNUCKLE HUB + BEARING	1	na	\$233.64
15	FRONT RH LOWER ARM - STRAIGHT	1	na	\$242.99
16	FRONT RH LOWER ARM - CURVED	1	na	\$224.29
17	FRONT RH UPPER ARM	1	na	\$121.49
18	FRONT RH STEERING TIE ROD END	1	na	\$121.49
SUB TOTAL				\$5,392.00
LESS 10%				-\$539.20
PARTS TOTAL				\$4,852.80

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1	na	\$55.00
2	FRONT BUMPER LOWER CLIPS	1	na	\$50.00
3	FRONT FENDER LINER CLIPS	1	na	\$50.00
4	FRONT PARKING SENSOR MOUNTING BRACKET SET	1	na	\$200.00
S/N TOTAL				\$355.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC. \$700.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT RH FENDER, ETC \$650.00

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 8919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 5-9-2024
 Vehicle No: SNG5671C
 Model: Tesla Model 3
 Chassis: LRW3F7FS2NC601751
 Reg.Year: 18.8.2022

Third Party Insurer: AIG
 Third Party Veh No: SMR657G
 Date of Accident: 5/9/2024
 Estimator: Loong
 Surveyor:

LABOUR CHARGES TO REMOVE & REPLACE FRONT PARKING SENSOR & ETC.	\$100.00	601
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$100.00	301
TO REMOVE AND REFIT FRONT UNDERCARRIAGE PARTS TO ENABLE REPAIR	na \$300.00	X
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$100.00	201
TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	na \$120.00	X
TO R&R TYRE RIM	na \$100.00	X
TO READJUST AND REALIGN HEADLAMP AIM	\$100.00	401

LABOUR TOTAL \$2,270.00

TOTAL \$7,477.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: