



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: HELENA TAN

Ref: CS/INC24090139/Avh3e2(N)

Date: 16/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJM 1089B	Veh. Inspected	SLD 1778U
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1289716-001	Excess (\$)	0.00
Assign From	HELENA TAN	Assign Date	09/09/2024

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ GLA200	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WDC1569432J477741	Colour	GREY
Odometer	122518 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	285/40 R19	GOODYEAR	6 mm
L/H Front Tyre	285/40 R19	GOODYEAR	6 mm
R/H Rear Tyre	285/40 R19	GOODYEAR	6 mm
L/H Rear Tyre	285/40 R19	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/08/2024	Inspect Date / Time	30/09/2024 (02:40 PM)
Survey held at	SIN YU SIN WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-52 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days