

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

TO	: AIG	DATE	28/8/2024
VEHICLE NO	: SMN4281B (2019)		Daphne
VEHICLE MODEL	: TOYOTA LAND CRUISER		
CHASSIS NO	: URJ2024187615		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Debond</i>	1	\$ 2,850.60	\$ 2,850.60
2	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 78.50	\$ 157.00
3	REAR BUMPER TOP PAD <i>Debond</i>	1	\$ 298.20	\$ 298.20
4	REAR BUMPER LAMP <i>RH could</i>	2	\$ 257.40	\$ 514.80
5	REAR BUMPER SENSOR <i>2 pieces damaged</i>	4	\$ 302.20	\$ 1,208.80
6	REAR BUMPER BEAM <i>Debond</i>	1	\$ 180.90	\$ 180.90
7	REAR BUMPER CENTRE GUIDE <i>Cracked</i>	1	\$ 254.50	\$ 254.50
8	REAR BUMPER REINFORCEMENT <i>RHS</i>	1	\$ 531.50	\$ 531.50
9	TAILLAMP <i>RH Cracked</i>	2	\$ 1,281.10	\$ 2,562.20
10	TAILGATE (UPPER) <i>RHS</i>	1	\$ 3,501.70	\$ 3,501.70
11	TAILGATE (UPPER) LOCK <i>new</i>	1	\$ 382.90	\$ 382.90
12	TAILGATE (UPPER) CHROME MOULDING <i>new</i>	1	\$ 518.50	\$ 518.50
13	TAILGATE (UPPER) REFLECTOR <i>new</i>	2	\$ 1,080.40	\$ 2,160.80
14	TAILGATE (UPPER) SPOILER <i>new</i>	1	\$ 1,645.60	\$ 1,645.60
15	TAILGATE (UPPER) GLASS MOULDING <i>new</i>	1	\$ 187.90	\$ 187.90
16	TOYOTA LOGO <i>new</i>	1	\$ 85.80	\$ 85.80
17	TAILGATE (LOWER) <i>Debond</i>	1	\$ 3,488.20	\$ 3,488.20
18	V8 EMBLEM <i>new</i>	1	\$ 78.40	\$ 78.40
19	UTILITY TRAY <i>Debond</i>	1	\$ 396.40	\$ 396.40
20	REAR END PANEL <i>RHS</i>	1	\$ 1,055.90	\$ 1,055.90

TOTAL PRICE: \$ 22,060.60

LESS 25% \$ 5,515.15

SUB TOTAL PRICE: \$ 16,545.45

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
5	REAR END PANEL SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
6	TAILGATE (UPPER) CHROME MOULDING CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
7	TAILGATE (UPPER) SPOILER SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
8	TAILGATE (UPPER) GLASS SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00

TOTAL: \$ 240.00

90

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,400.00	500	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	600	
3	WIRING CHECK	\$ 50.00	30	
4	TO APPLY TUFF COAT	\$ 150.00	30	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
6	TO REMOVE REAR CAMERA	\$ 100.00	50	
7	TO REMOVE UPHOLSTERY	\$ 150.00	X	
8	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	60	
9	TO REMOVE TAILGATE GLASS	\$ 180.00	X	

TOTAL: \$ 3,680.00

ESTIMATE REPORT

TOTAL PARTS COST: \$ 16,785.45

TOTAL LABOUR COST: \$ 3,680.00

TOTAL REPAIR COST: \$ 20,465.45

1340

total 8124.50

2/s: 651k.

0.5 days.

6.51k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: