

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 16 Sep 2024

**Preliminary Advice**

Insured Vehicle No	: FBG7340L	Accident Date	: 22/08/2024
TP Vehicle No	: SFM13Z	Assignment Date	: 09/09/2024
Make	: TOYOTA LEXUS	Est. Duration of Repair	: 3
Date of Inspection	: 10/09/2024		
Inspection At	: TECHNO AUTOMOTIVE PRIVATE LIMITED 60 JALAN LAM HUAT #05-56 CARROS CENTRE SINGAPORE 737869		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,734.99
Revised Amount	:S\$	7,426.79
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,426.79
Lump Sum Repair	:S\$	5,900.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical for repair  
( ) The vehicle is not economical for repair  
( ) Part-by-Part repair  
( X ) Lump Sum repair
- ( X ) The above survey was conducted on a 'without prejudice' basis.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.