

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI24090142/EQP3M4

Date: 19/09/2024

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MR005901	
Claimant Vehicle No :	SHB3035A	Insured Vehicle No :	SMW2083Y	
Date of Loss:	06/09/2024	Nature of Claim:	TP	Claim No: M2405137

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB3035A	Engine No:	2ZRS053595
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Chassis No:	JTDKB3FU103560350
Reg. Date:	17/08/2017 (Man. Year: 2017)	Odometer:	0 km
Colour:	Yellow		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,148.92	1,148.92	0.00	0.00
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	240.00	160.00	80.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,400.92	1,320.92	80.00	5.71
Approved Total (Overridden) (S\$)		1,050.00		
(S\$)	1,400.92	1,050.00	350.92	25.05
+ GST 9.00/9.00% (S\$)	126.08	94.50	31.58	25.05
Nett Amount (S\$)	1,527.00	1,144.50	382.50	25.05

INSPECTION

Date of Assignment:	09/09/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	09/09/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang)
			59 Loyang Drive
			Singapore 508969
Estimated Period of Repair:	1.0 days		

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2024)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB3035A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT SIDE MIRROR ASSY RH	Broken	1,390.10 FL	*1,390.10 FL
2	1		*FRT SIDE MIRROR COVER RH	Missing	141.80 FL	*141.80 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					1,531.90	1,531.90
- List Item Discount on L Items 25.00/25.00% (S\$)					382.98	382.98
Total Parts (S\$)					1,148.92	1,148.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	120.00	80.00
2	SPRAYPAINT CHARGES	New	120.00	80.00
Gross Labour Cost (\$\$)			240.00	160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >