

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP / TP RES / OD RES / EVA / INV / MV

To in Vehicle No: _____

at Work / Home / Other

or _____

Insured: _____

Policy No: _____

Claim: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remarks: Vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLN188SR Yr Regn: 2017, April

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel C.D. 1496

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 151529 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU11117488

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.J.

09/09/24

Survey held at

HD Perfect

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP III

COE Expiry:

Estimate given during: Yes (✓)

1st Survey: No ()

MV:

PV:

Nett:

3107.

Date/Time, File Pass to?

☐ : Preli. Report

1) Date/Time, File Return to?

☐ : Final Report

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inve (\$

Survey Fee:

Transportation:

3 + RS \$

Photos

Others

Report Format:


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 09.09.2024

TO : INDIA INTERNATIONAL MOTOR CLAIMS DEPTS
VEHICLE NO : SLN1885R
MODEL : HONDA VEZEL
DATE OF ACCIDENT : 07.09.2024
TIME OF ACCIDENT : 16:25 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dehnd</i>	1	\$ 865.50	\$ 865.50 <i>745</i>
2	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 178.20	\$ 356.40 <i>✓</i>
3	REAR BUMPER SIDE <i>new</i> <i>ton</i>	2	\$ 230.00	\$ 460.00 <i>✓</i>
4	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 57.00	\$ 114.00 <i>+</i>
5	TAIL LAMP <i>cut</i>	2	\$ 503.90	\$ 1,007.80 <i>-950</i>
6	TAIL LAMP PANEL <i>2HP</i>	2	\$ 268.00	\$ 536.00 <i>+</i>
7	TAIL LAMP INNER PANEL <i>1HP</i>	2	\$ 479.00	\$ 958.00 <i>+</i>
8	TAILGATE <i>Dehnd</i>	1	\$ 1,100.00	\$ 1,100.00 <i>✓</i>
9	TAILGATE LOGO <i>new</i>	1	\$ 65.00	\$ 65.00 <i>+</i>
10	TAILGATE OUTER GARNISH <i>new</i>	1	\$ 267.80	\$ 267.80 <i>+</i>
11	TAILGATE SIDE LAMP <i>cut</i>	2	\$ 287.40	\$ 574.80 <i>✓</i>
12	TAILGATE DAMPER <i>new</i>	2	\$ 180.70	\$ 361.40 <i>+</i>
13	TAILGATE INNER HOLDER <i>new</i>	1	\$ 52.00	\$ 52.00 <i>+</i>
14	TAILGATE WIRE HARNESS <i>new</i>	1	\$ 683.00	\$ 683.00 <i>+</i>
15	TAILGATE STOPPER <i>new</i>	2	\$ 19.00	\$ 38.00 <i>+</i>
16	TAILGATE TOP LOCK <i>Dehnd</i>	1	\$ 180.00	\$ 180.00 <i>+</i>
17	TAILGATE LOWER LOCK <i>new</i>	1	\$ 24.70	\$ 24.70 <i>+</i>
18	TAILGATE INNER TRIM <i>new</i>	1	\$ 263.40	\$ 263.40 <i>✓</i>
19	TAILGATE INNER SIDE TRIM <i>new</i>	2	\$ 48.20	\$ 96.40 <i>+</i>
20	TAILGATE WEATHER STRIP <i>cut</i>	1	\$ 168.40	\$ 168.40 <i>✓</i>

TO : INDIA INTERNATIONAL MOTOR CLAIMS DEPTS
 VEHICLE NO : SLN1885R
 MODEL : HONDA VEZEL
 DATE OF ACCIDENT : 07.09.2024
 TIME OF ACCIDENT : 16:25 HOURS

21	TAILGATE WINDSCREEN MOULDING (SET) <i>an</i>	1	\$ 164.00	\$ 164.00	✓
22	TAILGATE LOCK DETECTOR <i>anld</i>	1	\$ 379.00	\$ 379.00	✓
23	REAR FENDER INNER TRIM <i>anld</i>	2	\$ 399.10	\$ 798.20	✓
24	REAR FENDER COWLING <i>new</i>	2	\$ 150.20	\$ 300.40	+
25	REAR FENDER ARCED GARNISH <i>new</i>	2	\$ 184.70	\$ 369.40	+
26	BUZZER <i>anld</i>	1	\$ 109.00	\$ 109.00	✓
27	REAR END PANEL <i>Dented</i>	1	\$ 530.00	\$ 530.00	✓
28	REAR END PANEL TOP GARNISH <i>anld</i>	1	\$ 146.30	\$ 146.30	✓
29	REAR FLOOR PANEL <i>Reps Buckled</i>	1	\$ 1,130.00	\$ 1,130.00	✓
30	REAR FLOOR TOWING PANEL <i>new</i>	1	\$ 545.00	\$ 545.00	+
31	REAR FLOOR BOTTOM CROSS MEMBER <i>new</i>	1	\$ 250.80	\$ 250.80	+
32	REAR FLOOR SIDE PANEL <i>new</i>	2	\$ 297.60	\$ 595.20	+
33	REAR FLOOR PANEL BOTTOM GARNISH <i>anld</i>	1	\$ 269.00	\$ 269.00	✓
34	REAR FLOOR PANEL TOP BOARD <i>Dented</i>	1	\$ 325.70	\$ 325.70	✓
35	REAR STORAGE SPONGE <i>anld</i>	1	\$ 156.40	\$ 156.40	✓
36	EDLC MODULE <i>341</i>	1	\$ 1,432.70	\$ 1,432.70	+
37	REAR CHASSIS MEMBER <i>341</i>	1	\$ 797.40	\$ 797.40	+
38	REAR EXHAUST INSULATOR <i>341</i>	1	\$ 155.00	\$ 155.00	+
39	REAR EXHAUST PIPE <i>341</i>	1	\$ 980.00	\$ 980.00	+
40	REAR EXHAUST MOUNTING <i>341</i>	4	\$ 29.40	\$ 117.60	+
41	REAR EXHAUST GASKET (SET) <i>341</i>	1	\$ 80.00	\$ 80.00	+

TOTAL PRICE \$ 17,803.70
 LESS 20% \$ 3,560.74
SUB TOTAL PRICE \$ 14,242.96

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	30
2	TAILGATE OUTER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
3	TAILGATE INNER TRIM BOARD CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	30
4	TAILGATE WINDSCREEN SEALANT <i>341</i>	1	\$ 80.00	\$ 80.00	40
5	TAILGATE WINDSCREEN INNER SEAL <i>341</i>	1	\$ 60.00	\$ 60.00	30
6	TAIL LAMP CLIP (SET) <i>341</i>	1	\$ 40.00	\$ 40.00	+
7	TAIL LAMP PANEL SEALANT <i>new</i>	2	\$ 60.00	\$ 120.00	+

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLN1885R**
 MODEL : **HONDA VEZEL**
 DATE OF ACCIDENT : 07.09.2024
 TIME OF ACCIDENT : 16:25 HOURS

8	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>✓</i>
9	REAR FENDER COWLING CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	<i>T</i>
10	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	<i>20</i>
11	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
12	REAR FLOOR PANEL SEALANT <i>new</i>	1	\$ 350.00	\$ 350.00	<i>✓</i>
13	REAR FLOOR PANEL BOTTOM GARNISH CLIP (SET)	1	\$ 60.00	\$ 60.00	<i>30</i>
14	REVERSE CAMERA <i>new</i>	1	\$ 480.00	\$ 480.00	<i>T</i>
15	REVERSE SENSOR (SET) <i>new</i>	1	\$ 220.00	\$ 220.00	<i>20</i>

TOTAL \$ 1,880.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	<i>1200</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	<i>800</i>
3	TUFF COAT	\$ 250.00	<i>80</i>
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	<i>80</i>
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REAR CHASSIS ALIGNMENT	\$ 250.00	<i>X</i>
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	<i>✓</i>
9	TRANSFER TAILGATE MECHANISM	\$ 80.00	<i>60</i>

TO : **INDIA INTERNATIONAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLN1885R**
 MODEL : **HONDA VEZEL**
 DATE OF ACCIDENT : 07.09.2024
 TIME OF ACCIDENT : 16:25 HOURS

10	REMOVE AND REFIX REAR VIDEO RECORDER	\$ 80.00	50
11	CONDUCT WATER LEAKAGE TEST	\$ 100.00	+
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	+

TOTAL \$ 5,490.00

TOTAL PARTS COST : \$ 16,122.96
 TOTAL LABOUR COST : \$ 5,490.00
 TOTAL REPAIR COST : \$ 21,612.96

Adrian C
L/S 09/09/24
09 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: