9/19/24, 5:32 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI24090144/EVP3M4

Date: 19/09/2024

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MAB00167 **Claimant Vehicle**

SHD3858G Insured Vehicle No: SMJ5103Y No:

Date of Loss: 06/09/2024 Nature of Claim: TP Claim No: M2405147

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHD3858G Reg No:

HYUNDAI AE IONIQ HEV, 1.6 DCT (A) Make & Model: Engine No: G4LEJU132410

KMHC851CVKU121844 Reg. Date: 11/12/2018 (Man. Year: 2018) Chassis No:

Colour: Blue Odometer: 356855 km

Engine Capacity: 1580 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes **Engine Modification:** Pre-accident Condition: Handbrake (Serviceable): Yes Nο Average

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Rear Left Side: West Lake 6 mm West Lake 6 mm Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts | 3,626.36 | 2,974.28 | 652.08 | 17.98 |
| Miscellaneous Items | 12.00 | 12.00 | 0.00 | 0.00 |
| Labour | 1,500.00 | 990.00 | 510.00 | 34.00 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 5,138.36 | 3,976.28 | 1,162.08 | 22.62 |
| Approved Total (Overridden) (S\$) | | 3,150.00 | | |
| (S\$) | 5,138.36 | 3,150.00 | 1,988.36 | 38.70 |
| + GST 9.00/9.00% (S\$) | 462.45 | 283.50 | 178.95 | 38.70 |
| Nett Amount (S\$) | 5,600.81 | 3,433.50 | 2,167.31 | 38.70 |

INSPECTION

Date of Assignment: 09/09/2024 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 09/09/2024 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: **CHEN TSUE YEE** Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Sep 2024)

Parts: 143 HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD3858G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|---------|-----------------|----------------------------|---------------------------------|-------------|--------------|
| 1 | 1 | | *FRT BUMPER ASSY | Broken | 481.10 FL | *481.10 FL |
| 2 | 10 | | *FRT BUMPER CLIPS | Necessary | 22.00 FL | *22.00 FL |
| 3 | 1 | | *FRT BUMPER UPPER MOULDING | Cut | 368.50 FL | *368.50 FL |
| 4 | 1 | | *FRT FENDER LH | Repair | 588.80 FL | *- FL |
| 5 | 1 | | *FRT FENDER EMBLEM LH | Not Necessary | 26.60 FL | *- FL |
| 6 | 1 | | *FRT FENDER SHIELD LH | Not Necessary | 164.70 FL | *- FL |
| 7 | 1 | | *HEADLAMP ASSY LH | Cut | 2,110.30 FL | *2,110.30 FL |
| 8 | 1 | | *FRT BUMPER BRACKET LH | Not Necessary | 35.00 FL | *- FL |
| 9 | 1 | | *FRT FOG LAMP LH | Cut | 642.50 FL | *642.50 FL |
| 10 | 1 | | *FRT FOG LAMP GRILLE LH | Cut | 93.45 FL | *93.45 FL |
| F=Fra | anchise | part. L=ListIte | mDisc. | Sub Total (S\$) | 4,532.95 | 3,717.85 |
| | | | - List Item Discoun | t on L Items 20.00/20.00% (S\$) | 906.59 | 743.57 |
| | | | | Total Parts (S\$) | 3,626.36 | 2,974.28 |
| | | | Report was unsubmit | ted during this print-out. | | |

Recommended Miscellaneous Items

| No Qty Particulars | | Repairer's | Amount |
|--------------------------|-----------------|------------|--------|
| Miscellaneous Items | | | , |
| 1 1 OD/TP Case (Insurer) | | 12.00 | 12.00 |
| | Sub Total (S\$) | 12.00 | 12.00 |

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|--------------------|-------------------------|------------|--------|
| Lab | our Items | | | |
| 1 | PANEL BEATING | New | 800.00 | 380.00 |
| 2 | SPRAYPAINT CHARGES | New | 600.00 | 580.00 |
| 3 | TUFF KOTE | New | 50.00 | 0.00 |
| 4 | CHECL WIRING | New | 50.00 | 30.00 |
| | | Gross Labour Cost (S\$) | 1,500.00 | 990.00 |

Report was unsubmitted during this print-out. < END OF ESTIMATES >