

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600**Our File No:** CS/ICS24090146/KQP3E2**Date:** 05/12/2024REFERENCE

Insured/Claimant:	KANDA SAMY SOUNDARARAJAN	Policy No:	MPC23P00213400
Date of Loss:	30/08/2024	Nature of Claim:	OD
		Claim No:	DMPC2401145H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNG5537H	Engine No:	CYG004962
Make & Model:	AUDI A6, 1.8 TFSI S-tronic (A)	Chassis No:	WAUZZZ4GXFN083650
Reg. Date:	31/08/2015 (Man. Year: 2015)	Odometer:	178075 km
Colour:	Metallic White		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$43,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/40 R19	Rear Tyre Size:	255/40 R19
Front Left Side:	Comforser 9 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Comforser 9 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,579.50	13,579.50	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	1,100.00	200.00	15.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,879.50	14,679.50	200.00	1.34
Approved Total (Overridden) (\$\$)		11,700.00		
- Excess (\$\$)	750.00	0.00	750.00	100.00
(\$\$)	14,129.50	11,700.00	2,429.50	17.19
+ GST 9.00/9.00% (\$\$)	1,271.66	1,053.00	218.66	17.19
Nett Amount (\$\$)	15,401.16	12,753.00	2,648.16	17.19

INSPECTION

Date of Assignment:	09/09/2024	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
			Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	10/09/2024	Inspected At:	Blk 1019 #01-374/382, Yishun Industrial Park A
			Singapore 768761
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2024)
Parts:	143	AUDI A6 1.8 TFSI S-tronic (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNG5537H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 pc front bumper (WCP)	Buckled / Dented	1,140.00 F	*1,140.00 F
2	1		*1 pc RH headlamp (WCP)	Cracked	6,700.00 F	*6,700.00 F
3	1		*1 pc front right fender (WCP)	Bent	650.00 F	*650.00 F
4	1		*1 pc bonnet (WCP)	Bent	2,290.00 F	*2,290.00 F
Supplementary #1						
5	1		*1 PC RH HEADLAMP ECU (WCP)	Shorted	850.00 F	*850.00 F
6	1		*1 PC RH HEADLAMP FAN MOTOR (WCP)	Shorted	180.00 F	*180.00 F
7	1		*1 PC RH HEADLAMP POWER MODULE (WCP)	Shorted	250.00 F	*250.00 F
8	1		*1 PC RH HEADLAMP POWER MODULE DAYLIGHT (WCP)	Shorted	285.00 F	*285.00 F

F=Franchise part.

Sub Total (\$\$)	12,345.00	12,345.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	1,234.50	1,234.50
Total Parts (\$\$)	13,579.50	13,579.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Panel beating	New	300.00	300.00
2	Putty & respray	New	700.00	600.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
3	LABOUR TO REMOVE, REFIT AND RESET HEADLAMP SYSTEM.	New	300.00	200.00
Gross Labour Cost (S\$)			1,300.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >