



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)
Policy No: MPC23P00213400
Vehicle Reg. No.: SNG5537H
Driver Age/Info: 44 / MALE
TP Injury Involved? NO
Insured/Claimant: KANDA SAMY SOUNDARARAJAN
Driver: KANDA SAMY SOUNDARARAJAN

Ref. No: OD/ECICS
Date of Loss: 30/08/2024
Driveable?
Party At Fault: UNKNOWN
Third Party Involved? YES
Contact No: +6598593376

Make/Model: AUDI A6, 1.8 TFSI S-TRONIC (A)
Vehicle Colour: WHITE
Engine No: CYG004962
Odometer: 0 KM

Vehicle Reg. Date: 31/08/2015
Chassis No: WAUZZZ4GXFN083650

Paint Type:
Total Loss? NO
Est. Duration of Repair (day) 0

*Not Notified
1/1/24
Repair After Paint
4 days
Ex TBA*

Description of Accident/Loss: REFER TO GIA REPORT
Remarks: VEHICLE AT YISHUN WORKSHOP
Present Location: CHENG HOE MOTOR PTE LTD (YISHUN)

COST OF CLAIMS

	Amount
Parts	11,858.00
Miscellaneous Items	0.00
Labour	1,000.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	12,858.00
- Excess (S\$)	750.00
(S\$)	12,108.00
+ GST 9.00% (S\$)	1,089.72
Nett Amount (S\$)	13,197.72

This claim is handled by: DORLYN LI YAZHU

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Sep 2024)
 Parts: 143 AUDI A6 1.8 TFSI S-tronic (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Hoe Motor Pte Ltd/SNG5537H/30/09/2024 19:32
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC RH HEADLAMP ECU	Shom 0.00	0.00	*850.00 F
2	1		*1 PC RH HEADLAMP FAN MOTOR	Shom 0.00	0.00	*180.00 F
3	1		*1 PC RH HEADLAMP POWER MODULE	h 0.00	0.00	*250.00 F
4	1		*1 PC RH HEADLAMP POWER MODULE DAYLIGHT	h 0.00	0.00	*285.00 F
Sub Total (S\$)						1,565.00
+ Margin on L,N Items 10.00% (S\$)						156.50
Total Parts (S\$)						1,721.50

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SNG5537H/30/09/2024 19:32. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR TO REMOVE, REFIT AND RESET HEADLAMP SYSTEM.	New	300.00
Gross Labour Cost (S\$)			300.00

2006

Cheng Hoe Motor Pte Ltd/SNG5537H/30/09/2024 19:32. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Sep 2024)
 Parts: 143 AUDI A6 1.8 TFSI S-tronic (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Hoe Motor Pte Ltd/SNG5537H/09/09/2024 14:45
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

SNG 5537H
0DIECICS

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc front bumper	0.00	0.00	Bul/da *1,140.00 F ✓
2	1		*1 pc RH headlamp	0.00	0.00	CM *6,700.00 F ✓
3	1		*1 pc front right fender	0.00	0.00	B1 *650.00 F ✓
4	1		*1 pc bonnet	0.00	0.00	B2 *2,290.00 F ✓
Sub Total (\$)						10,780.00
+ Margin on L,N Items 10.00% (\$)						1,078.00
Total Parts (\$)						11,858.00

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SNG5537H/09/09/2024 14:45. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Panel beating	New	300.00 ✓
2	Putty & respray	New	600 700.00
Gross Labour Cost (\$)			1,000.00

Cheng Hoe Motor Pte Ltd/SNG5537H/09/09/2024 14:45. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: