



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24090147/Anp3e2
16 RAFFLES QUAY	Date:	22/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 2261U	Veh. Inspected	SNN 8093P
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24007798MFCT	Excess	\$0.00
Assign From	HARMINDER	Assign Date	06/09/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ CLA 200	C.C	1595
Engine No.	27091030310315	Year of Reg.	22/01/2014
Chassis No.	WDD1173432N060157	Colour	BLACK
Odometer	135831 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/35 R19	MICHELIN	6
L/H Front Tyre	235/35 R19	MICHELIN	6
R/H Rear Tyre	235/35 R19	MICHELIN	6
L/H Rear Tyre	235/35 R19	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/09/2024	Inspection Date	09/09/2024
Survey held at	SM AUTOMOTIVE - BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days