

SM INTEGRATED PTE LTD

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_INTEGRATED@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

UEN: 202235196G

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 03/09/2024

Estimated repair cost for vehicle no: SNN8093P MERCEDES BENZ CLA 200 (R18 BI)

CHASSIS: WDD1173432N060157 (2013)

SUPPLEMENTARY

S/N	Qty	Items	U/price	Amount
1	1	FRONT BUMPER UNDER COVER <i>torn</i>	\$178.00	\$178.00 ✓
2	1	FRONT BUMPER LOWER LIP <i>LH</i> <i>cracked</i>	\$780.00	\$780.00 <i>450</i>
3	1	FRONT BUMPER LOWER LIP INNER BRACKET LH <i>broken</i>	\$320.00	\$320.00 +
4	1	FRONT BUMPER FOG LAMP SUPPORT GARNISH LH <i>cracked</i>	\$121.00	\$121.00 ✓

Front Bumper lower Grille *480* ✓
cracked

TOTAL :	\$1,399.00
LESS 10 %	\$139.90
SUB-TOTAL :	\$1,259.10

1229

Supplementary: 1106.10