

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Authorised
Punmy After Rain
1 day
\$315.00

ESTIMATE

3RD PARTY

MSIG INSURANCE (SINGAPORE) PTE LTD
ATTN: ACCIDENT CLAIMS DEPARTMENT

FIRST REGISTRATION: 22.04.2016

DATE : 18.06.2024
VEHICLE NO : SLB7964U
VEH MAKE/MODEL : TOYOTA HARRIER
YOM : 2015
CHASSIS NO : ZSU600070891
DATE OF ACCIDENT : 19.05.2024

NO	QTY	DESCRIPTION	AMOUNT \$
		LIST PRICE:-	
1	1	FRONT GRILLE ASSY	\$ 911.00 X
2	1	FRONT BUMPER	\$ 934.00 X
3	1	FRONT BUMPER SIDE RETAINER LH	\$ 143.20 X
4	1	FRONT BUMPER SIDE RETAINER RH	\$ 143.20 X
5	1	FRONT BUMPER LOWER GRILLE	\$ 369.20 X
6	1	FRONT BUMPER LOWER LIP	\$ 402.70 X
7	2	TOWING COVER	\$ 68.60 X
8	1	FRONT LH HEADLAMP	\$ 2,196.50 X
9	1	FRONT LH HEADLAMP LOWER BRACKET	\$ 87.10 X
10	1	FRONT RH HEADLAMP	\$ 2,196.50 X
11	1	FRONT RH HEADLAMP LOWER BRACKET	\$ 87.10 X
12	1	FRONT REINFORCEMENT BAR	\$ 644.20 X
13	1	FRONT LOCK BRACE PANEL/BACKET	\$ 311.80 X
14	1	FRONT RADIATOR TOP GARNISH	\$ 448.50 X
15	1	FRONT SUPPORT PANEL	\$ 1,243.90 X
16	1	AIRCON CONDENSOR	\$ 2,368.10 X
17	1	RADIATOR	\$ 3,394.10 X
18	1	NUMBER PLATE GARNISH	\$ 230.00 X
19			
20			
21			
22			
23			
24			
25			
26			
27			
28			
TOTAL - LIST ITEM			\$ 16,179.70
25% LIST PRICE:-			\$ 4,044.93
TOTAL			\$ 12,134.78

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

3RD PARTY

MSIG INSURANCE (SINGAPORE) PTE LTD
ATTN: ACCIDENT CLAIMS DEPARTMENT

FIRST REGISTRATION: 22.04.2016

DATE : 18.06.2024
VEHICLE NO : SLB7964U
VEH MAKE/MODEL : TOYOTA HARRIER
YOM : 2015
CHASSIS NO : ZSU600070891
DATE OF ACCIDENT : 19.05.2024

		<u>SPECIAL NETT ITEMS:-</u>		
1	SET	FRONT BUMPER CLIPS	\$ <i>nn</i> 50.00	X
2	2 SET	FRONT FENDER INNER SHIELD CLIPS	\$ <i>nn</i> 50.00	X
3	SET	FRONT NUMBER PLATE WITH HOLDER	\$ <i>B</i> 50.00	4552
4	SET	FRONT RADIATOR TOP GARNISH CLIPS	\$ <i>nn</i> 20.00	X
5				
6				
		Total - SN Item	\$ 170.00	
		<u>Labour Charges:-</u>		
1		SPRAY PAINT ON ALL AFFECTED AREA	\$ 1,000.00	2201
2		LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	\$ 1,000.00	501
3		TO CHECK WIRING SYSTEM	\$ <i>nn</i> 100.00	X
		TO APPLY ANTI RUST TREATMENT	\$ <i>nn</i> 120.00	X
4		TO REMOVE/REFIX/REPLACE RADIATOR COWLING ASSY, AIRCON CONDENSOR (PIPING, HOSE, TOP UP AIRCON GAS, REFILL COOLANT & ETC	\$ <i>nn</i> 350.00	X
5				
6				
7				
		Total - L/C	\$ 2,570.00	
		Sub-Total	\$ 14,874.78	
		9% GST	\$ 1,338.73	
		Total	\$ 16,213.50	