

ASS. REC. BY:

REF:

C/MSG 24060151/Kap3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1-B.1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/10 @ 315.00 Cash (Red # 15898.50, 98%)

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

MER-TP

315

TOTAL

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Authorized
Punmy After Rain
1 day
8315.00

ESTIMATE

3RD PARTY

MSIG INSURANCE (SINGAPORE) PTE LTD

ATTN: ACCIDENT CLAIMS DEPARTMENT

FIRST REGISTRATION: 22.04.2016

DATE : 18.06.2024
VEHICLE NO : SLB7964U
VEH MAKE/MODEL : TOYOTA HARRIER
YOM : 2015
CHASSIS NO : ZSU600070891
DATE OF ACCIDENT : 19.05.2024

NO	QTY	DESCRIPTION	AMOUNT \$	
		LIST PRICE:-		
1	1	FRONT GRILLE ASSY	\$ 911.00	X
2	1	FRONT BUMPER	\$ 934.00	X
3	1	FRONT BUMPER SIDE RETAINER LH	\$ 143.20	X
4	1	FRONT BUMPER SIDE RETAINER RH	\$ 143.20	X
5	1	FRONT BUMPER LOWER GRILLE	\$ 369.20	X
6	1	FRONT BUMPER LOWER LIP	\$ 402.70	X
7	2	TOWING COVER	\$ 68.60	X
8	1	FRONT LH HEADLAMP	\$ 2,196.50	X
9	1	FRONT LH HEADLAMP LOWER BRACKET	\$ 87.10	X
10	1	FRONT RH HEADLAMP	\$ 2,196.50	X
11	1	FRONT RH HEADLAMP LOWER BRACKET	\$ 87.10	X
12	1	FRONT REINFORCEMENT BAR	\$ 644.20	X
13	1	FRONT LOCK BRACE PANEL/BACKET	\$ 311.80	X
14	1	FRONT RADIATOR TOP GARNISH	\$ 448.50	X
15	1	FRONT SUPPORT PANEL	\$ 1,243.90	X
16	1	AIRCON CONDENSOR	\$ 2,368.10	X
17	1	RADIATOR	\$ 3,394.10	X
18	1	NUMBER PLATE GARNISH	\$ 230.00	X
19				
20				
21				
22				
23				
24				
25				
26				
27				
28				
			TOTAL - LIST ITEM	\$ 16,179.70
			25%	\$ 4,044.93
			TOTAL	\$ 12,134.78

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

