


Company Reg No: 202136905K

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 03.09.2024

TO	: CHINA TAIPING	MOTOR CLAIMS DEPTS
VEHICLE NO	: SU8228L	
MODEL	: PORSCHE MACAN PDK CYP E5	
DATE OF ACCIDENT	: 30.08.2024	
TIME OF ACCIDENT	: 21:15 HOURS	

E : 03.09.2024

WP1222552KL B06167

Xiao Tony

WE APPEND HEREBUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>born</i>	1	\$ 1,850.00	\$ 1,850.00
2	FRONT BUMPER DAY LIGHT LH <i>new</i>	1	\$ 740.00	\$ 740.00
3	FRONT BUMPER DAY LIGHT UPPER GARNISH LH <i>new</i>	1	\$ 493.00	\$ 493.00
4	FRONT BUMPER DAY LIGHT LOWER GARNISH LH <i>new</i>	1	\$ 488.00	\$ 488.00
5	FRONT BUMPER SENSOR <i>new</i>	2	\$ 315.00	\$ 630.00
6	FRONT BUMPER SENSOR HOLDER <i>new</i>	4	\$ 68.00	\$ 272.00
7	FRONT BUMPER AIR VENT GARNISH LH <i>new</i>	1	\$ 98.00	\$ 98.00
8	FRONT BUMPER AIR VENT INNER LOWER GARNISH LH <i>new</i>	1	\$ 87.00	\$ 87.00
9	FRONT BUMPER TOP COVER GARNISH (SIDE) LH <i>new</i>	1	\$ 430.00	\$ 430.00
10	FRONT BUMPER SPONGE <i>new</i>	1	\$ 290.00	\$ 290.00
11	FRONT BUMPER SIDE BRACKET <i>LH curved</i>	2	\$ 120.00	\$ 240.00
12	FRONT BUMPER UPPER CORNER BRACKET LH <i>new</i>	1	\$ 120.00	\$ 120.00
13	HEADLAMP LH <i>curved</i>	1	\$ 6,940.00	\$ 6,940.00
14	HEADLAMP LOWER BRACKET LH <i>new</i>	1	\$ 125.00	\$ 125.00
15	HEADLAMP RING RUBBER LH <i>new</i>	1	\$ 240.00	\$ 240.00
16	FRONT FENDER OUTER LH <i>Dented</i>	1	\$ 2,285.00	\$ 2,285.00
17	FRONT FENDER INNER LH <i>Revs</i>	1	\$ 2,863.00	\$ 2,863.00
18	FRONT FENDER COWLING LH <i>new</i>	1	\$ 279.90	\$ 279.90
19	BONNET <i>Revs</i>	1	\$ 5,890.00	\$ 5,890.00
20	BONNET LOGO <i>new</i>	1	\$ 450.00	\$ 450.00
21	BONNET HINGE <i>new</i>	2	\$ 200.00	\$ 400.00

$\frac{1}{+}$

+ +

- 720

f ✓ 4109.

+ f

- ✓ 1980

+ f

- 320

f

TO : **CHINA TAIPING** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SU8228L**
 MODEL : **PORSCHE MACAN PDK CYP E5**
 DATE OF ACCIDENT : 30.08.2024
 TIME OF ACCIDENT : 21:15 HOURS

22	BONNET LOCK	2	\$ 295.00	\$ 590.00	+
23	BONNET INSULATOR	1	\$ 678.00	\$ 678.00	+
24	FRONT ABS SENSOR LH	1	\$ 385.00	\$ 385.00	+
25	FRONT CROSSMEMBER	1	\$ 1,989.00	\$ 1,989.00	+
26	FRONT STEERING RACK AND PINION	1	\$ 7,755.00	\$ 7,755.00	+
27	FRONT KNUCKLE ARM LH	1	\$ 2,932.00	\$ 2,932.00	+
28	FRONT WHEEL HUP WITH BEARING LH	1	\$ 1,865.00	\$ 1,865.00	+
29	FRONT SHOCK ABSORBER LH	1	\$ 3,255.00	\$ 3,255.00	+
30	FRONT SHOCK ABSORBER HOUSING LH	1	\$ 1,862.00	\$ 1,862.00	+
31	FRONT LOWER ARM LH	1	\$ 1,843.00	\$ 1,843.00	+
32	FRONT CASTER ARM LH	1	\$ 1,922.00	\$ 1,922.00	+
33	FRONT UPPER ARM LH	1	\$ 1,385.00	\$ 1,385.00	+
34	FRONT DOOR SIDE MIRROR LH	1	\$ 2,864.20	\$ 2,864.20	+
35	FRONT DOOR LH	1	\$ 4,865.00	\$ 4,865.00	+
36	FRONT DOOR PROTECTOR LH	1	\$ 867.50	\$ 867.50	+
37	FRONT DOOR OUTER MOULDING LH	1	\$ 564.80	\$ 564.80	+

13047
11742.30

TOTAL PRICE \$ 51,671.90
 LESS 10% \$ 5,167.19
SUB TOTAL PRICE \$ 46,504.71

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE	1	\$ 80.00	\$ 80.00	+
2	FRONT BUMPER CLIP (SET)	1	\$ 150.00	\$ 150.00	+
3	FRONT BUMPER NUMBER PLATE GARNISH CLIP (SET)	1	\$ 80.00	\$ 80.00	+
4	FRONT BUMPER DAY LIGHT LOWER GARNISH CLIP (SE	1	\$ 80.00	\$ 80.00	+
5	FRONT BUMPER CENTER GRILLE CLIP (SET)	1	\$ 60.00	\$ 60.00	+
6	ENGINE UNDERCOVER CLIP (SET)	1	\$ 80.00	\$ 80.00	+
7	BONNET SEALANT	1	\$ 150.00	\$ 150.00	+
8	FRONT SUPPORT PANEL SEALANT	1	\$ 150.00	\$ 150.00	+
9	FRONT WHEEL TYRE	1	\$ 850.00	\$ 850.00	+
10	COOLANT	1	\$ 180.00	\$ 180.00	+
11	BRAKE OIL	1	\$ 120.00	\$ 120.00	+

Front Rem 1800 1200

TOTAL \$ 830.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1230

TO : **CHINA TAIPING** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SU8228L**
 MODEL : **PORSCHE MACAN PDK CYP E5**
 DATE OF ACCIDENT : 30.08.2024
 TIME OF ACCIDENT : 21:15 HOURS

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	600
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	800
3	REFOCUS HEADLAMP BEAM	\$ 60.00	x
4	REMOVE AND REFIX FRONT BUMPER SENSOR AND DISTANCE RESETTING	\$ 480.00	80
5	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 1,200.00	280
6	REMOVE AND REFIX POWER STEERING RACK AND PINION AND REPROGRAMING AND CODING	\$ 800.00	x
7	FOUR WHEEL ALIGNMENT	\$ 180.00	80
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 680.00	180

TOTAL \$ 6,800.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 47,334.71
 TOTAL LABOUR COST : \$ 6,800.00
 TOTAL REPAIR COST : \$ 54,134.71

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

SERVICE ADVISOR

IRENE
 HP : 8297 9787

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Adrian C
 s/s 04/09/24

Obtains.

total: 14992.30
 s/s: 12K

12K
 Collection