



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLC7430M

Tang Him Hwee

61 Pasir Ris Grove
#07-01
Singapore 518215

*Mobile: +6597839188

Vehicle & Document Information

WIP No 20061
Reg No/Reg Date SLC7430M / 25/05/2016
Date In/Mileage 24/09/2024/ 136965
Chassis No WDD2120362B305829
Engine No 27492030571838
Make/Model MB/MB E 250 2.0 SEDAN (W212) "EDITION E"
Colour/Trim 027 775 Iridium sil/ 042 241 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
CSI00003	Cash	06/12/2024/ 14:36	SJ	1208/ Foong Shiuh Jye					
Z REQUEST					Customer Request				
M BPNSUN					POLICY NO/ACC DATE :D24MTPV01006498 // 08 AUG 2024				
					DRIVE IN/TP: 12 AUG 2024 // SJK80S-U01				
					DATE IN/DATE SURVEY: 24 SEP 2024 // LKK RASUL				
					BY/AUTHORIZED ON :				
A BPILAB					DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				960.00
A BPIRES					RESPRAY BUMPER FRONT			0.05	800.00
A BPILAB					TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT				96.00
					*FRONT RIGHT				
A BPILAB					USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO			0.10	380.00
M BPNSUN					SUNDRIES				15.00
X FRONT TRIM BUMPER						1.00	1874.42	00.00	1874.42
X RIGHT HEADLAMP UNIT						1.00	5771.15	00.00	5771.15

Confirmed & accepted by

Nett 9,896.57
9% GST on 9896.57 890.69
Total Payable 10,787.26

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg