



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGS SINGAPORE 048581 ATTN: JASON TEA			Ref: CS/FCI24090151/Anp3m4(N) Date: 16/01/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3607P	Veh. Inspected	YP 4401U	
Policy No.	D-24101861MFCT	Coverage (\$)	0.00	
Claim No.	D24007888MFCT	Excess (\$)	0.00	
Assign From	JOANNE TAN	Assign Date	09/09/2024	
2. Vehicle Particulars & Condition				
Make & Model	HINO XZU710R-HKFMS3	c.c	4009	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JHHUCS3H80K018236	Colour	WHITE	
Odometer	195594 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	7.00 R16	GT	6 mm	
L/H Front Tyre	7.00 R16	GT	6 mm	
R/H Rear Tyre	7.00 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	7.00 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/09/2024	Inspection Date	10/09/2024	
Survey held at	CHIN CHUAN GARAGE BLK 3006 UBI ROAD 1 #01-338 SINGAPORE 408700			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		