

CHIN CHUAN GARAGE

Blk 3006 Ubi Rd 1, #01-336 Singapore 408700

H/P: 96736356 (Jack) Fax: 6747 8378

Reg. No.: 50600700J

Name: Dou Yee Enterprises (S) Pte Ltd

Address: c/o Blk 3006 Ubi Rd 1

#01-336 Singapore 408700

Date: 6-Sep-24

Vehicle No.: YP 4401 U

Model: Hino XZU710R-HKFMS3

TP 1st Cap
Hui Rong

Items:

S/N	Description	Amount
1 pc	Front bumper <i>Disturbed</i>	\$ 1,240.00
1 pc	Front bumper inner bracket RHS <i>Disturbed</i>	\$ 295.00
1 pc	Front bumper fog lamp RHS <i>Disturbed</i>	\$ 350.00
1 pc	Front bumper fog lamp inner garnish RHS <i>new</i>	\$ 135.00
1 pc	Front grille <i>new</i>	\$ 450.00
1 pc	Headlamp RHS <i>lt</i>	\$ 1,350.00
1 pc	Headlamp lower garnish RHS <i>new</i>	\$ 95.00
1 pc	Front corner panel RHS <i>Disturbed</i>	\$ 205.00
1 pc	Front side mirror with bracket assy RHS <i>new</i>	\$ 225.00
1 pc	Front door RHS <i>Disturbed</i>	\$ 1,450.00
1 set	Front door company sticker <i>new</i>	\$ 250.00
1 pc	Front door outer handle RHS <i>new</i>	\$ 185.00
1 pc	Front door signal lamp RHS <i>missing</i>	\$ 165.00
1 pc	Front door inner garnish RHS <i>deformed</i>	\$ 225.00
2 pcs	Front door upper and lower hinge RHS <i>new</i>	\$ 180.00
1 pc	Front step garnish RHS <i>lt</i>	\$ 265.00
1 pc	Front step garnish reflector RHS <i>lt</i>	\$ 95.00
1 pc	Front tyre mud flap RHS <i>lt</i>	\$ 220.00
1 pc	Rear tailgate aluminium corner assy RHS <i>Disturbed</i>	\$ 1,650.00
1 pc	Rear tailgate sliding door lock RHS <i>Disturbed</i>	\$ 165.00
1 pc	Rear tailgate side panel RHS <i>Repair</i>	\$ 480.00
1 pc	Rear tailgate side lock bracket RHS <i>Disturbed</i>	\$ 145.00
1 pc	Front door 616 sticker (Emblem) <i>Disturbed</i>	\$ 115.00
1 pc	Front door Euro 5 (Emblem) <i>Disturbed</i>	\$ 125.00
1 set	Rear tailgate sliding door sticker <i>new</i>	\$ 300.00
1 pc	Rear pillar <i>Repair</i>	repair
1 pc	Front pillar <i>Repair</i>	repair
1 pc	Front side mirror top bracket <i>new</i>	\$ 9,420.00
1 pc	Rear tailgate side step bracket RHS <i>new</i>	\$ 942.00
1 pc	Front fog lamp housing bracket RHS <i>new</i>	\$ 8,478.00
Less 10%		\$ 942.00
Total		\$ 8,478.00

S.N: 1050

CHIN CHUAN GARAGE

Blk 3006 Ubi Rd 1, #01-336 Singapore 408700

H/P: 96736356 (Jack) Fax: 6747 8378

Reg. No.: 50600700J

Labour

1)	To check wiring, lighting and re-setting	\$	50.00	30
2)	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damage consistent to the accident. (including all repair parts)	\$	1,200.00	800
3)	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$	1,200.00	700
		\$	<u>2,450.00</u>	

1530

Admin Lj
L/s 10/09/24

07 Pangs

Total: 7808.10
L/s 6.2K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: