

ASSIGNMENT

Front: _____ Date: _____

Estim: _____

OD / TP RES / OD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at W/O _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client Record)

Make of Vt: _____

(Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: YP4401U Yr Regn: 2016 / Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hino XZU710R C.D. 4009

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 195594 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 3HHUCS3H8OKO18236

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 7.00R16 GT

R: 7.00R16 BS

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 10/09/24

Survey held at Chin Chuan

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP 1st Cap.</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes ()</u>
	<u>1st Survey : No ()</u>
	<u>MV : 38K</u>
	<u>PV : 5.1K</u>
	<u>Nett : 32.9K</u>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Inve (\$)

Survey Fee: _____

Transportation: _____

3 + RS \$1

Photos

Others

Report Forward:

Report 24 HRS / 1.00 P.M.

CHIN CHUAN GARAGE

Blk 3006 Ubi Rd 1, #01-336 Singapore 408700

H/P: 96736356 (Jack) Fax: 6747 8378

Reg. No.: 50600700J

Name: Dou Yee Enterprises (S) Pte Ltd

Address: c/o Blk 3006 Ubi Rd 1

#01-336 Singapore 408700

Date: 6-Sep-24

Vehicle No.: YP 4401 U

Model: Hino XZU710R-HKFMS3

Items:

S/N	Description	Amount
1 pc	Front bumper <i>Disturbed</i>	\$ 1,240.00
1 pc	Front bumper inner bracket RHS <i>Disturbed</i>	\$ 295.00
1 pc	Front bumper fog lamp RHS <i>Disturbed</i>	\$ 350.00
1 pc	Front bumper fog lamp inner garnish RHS <i>new</i>	\$ 135.00
1 pc	Front grille <i>new</i>	\$ 450.00
1 pc	Headlamp RHS <i>new</i>	\$ 1,350.00
1 pc	Headlamp lower garnish RHS <i>new</i>	\$ 95.00
1 pc	Front corner panel RHS <i>Disturbed</i>	\$ 205.00
1 pc	Front side mirror with bracket assy RHS <i>new</i>	\$ 225.00
1 pc	Front door RHS <i>Disturbed</i>	\$ 1,850.00
1 set	Front door company sticker <i>new</i>	\$ 250.00
1 pc	Front door outer handle RHS <i>new</i>	\$ 185.00
1 pc	Front door signal lamp RHS <i>missing</i>	\$ 165.00
1 pc	Front door inner garnish RHS	\$ 225.00
2 pcs	Front door upper and lower hinge RHS <i>new</i>	\$ 180.00
1 pc	Front step garnish RHS <i>new</i>	\$ 265.00
1 pc	Front step garnish reflector RHS <i>new</i>	\$ 95.00
1 pc	Front tyre mud flap RHS <i>new</i>	\$ 220.00
1 pc	Rear tailgate aluminium corner assy RHS <i>Disturbed</i>	\$ 1,650.00
1 pc	Rear tailgate sliding door lock RHS <i>Disturbed</i>	\$ 165.00
1 pc	Rear tailgate side panel RHS <i>Disturbed</i>	\$ 480.00
1 pc	Rear tailgate side lock bracket RHS <i>Disturbed</i>	\$ 145.00
1 pc	Front door 616 sticker (Emblem) <i>new</i>	\$ 115.00
1 pc	Front door Euro 5 (Emblem) <i>new</i>	\$ 125.00
1 set	Rear tailgate sliding door sticker <i>new</i>	\$ 300.00
1 pc	Rear pillar <i>new</i>	repair
1 pc	Front pillar <i>new</i>	repair
1 pc	Front side mirror top bracket <i>new</i>	\$ 65.00
1 pc	Rear tailgate side step bracket RHS <i>new</i>	\$ 205.00
1 pc	Front fog lamp housing bracket RHS <i>new</i>	\$ 125.00
		Less 10%
		Total \$ 8,478.00

CHIN CHUAN GARAGE

Blk 3006 Ubi Rd 1, #01-336 Singapore 408700

H/P: 96736356 (Jack) Fax: 6747 8378

Reg. No.: 50600700J

Labour

1)	To check wiring, lighting and re-setting	\$	50.00	30
2)	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damage consistent to the accident. (including all repair parts)	\$	1,200.00	800
3)	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$	1,200.00	700
		\$	<u>2,450.00</u>	

Adrian Cj
1/s 10/09/24

07 Days