(08/11/13) wef REF: 6.2 / C						
ASS. REC. BY: Marcus REF: CS C7	24090152/UVh3					
ASSIGNMENT						
From: Date:	Veh No: 52 V 1899 J Yr Regn: 26/11/17					
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /					
OD (TP /)WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or A Mybrid					
To Inspect Vehicle No: SLV / 89 J	Make: Toyoto prius C c.c 1497					
at Workshop m/s 200M	Colour Shu A/C: Insured / Std / NI / NA					
of	Sp.Reading T/Radio: Insured / Std / NI / NA					
Insured: SNE 7705 L	Eng/No:					
Policy No.	C/No: JTDKD 3 B 3 X 0 1 6 0 (f) 8					
Claims No. SNM24D205048	Gen. Cond: Good / Fair / Poor / Burnt					
Sum Insured: Excess:	Steering: Increer / Jammed / Leaked / Burnt or					
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or					
Make of Veh:	Modi: Nil /S/Rim / STD A/Rim or					
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: GIA / PR Seen: Consistent?: Yes or No Est. Repairs: days Res.: Yes or No Lum Sum: % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Vehicle: IN / OUT Date: Person Contacted:	Tyre Size: F: R:					
Date / Time Action / Instruction De, 15/1/ 10/24 2/5 \$ 2300 inpured Eli-	(red 8047.59, 77%)					
	Days Of Repair: 4 Resurvey No. of Trip: Survey Fee:					
1) : Final Report	Resurvey No. of Trip: Survey Fee:					

Date/Time, File Pass to?	: Preli. Report
1)	: Final Report
Date/Time, File Return to?	
2)	
Report Format :	
Lump Sum / I.B.I:	(\$

Add Fee:

: Site Insp (\$

: Interview (\$

:Tech. Invs (\$

Others Weekend (\$

) Photos


TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	049E
Vehicle No.:	SLV1899J
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Sep 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS C HYBRID 1.5 CVT
Primary Colour:	Green
Manufacturing Year:	2017
Engine No.:	1NZ8309171
Chassis No.:	JTDKD3B3X01601898
Maximum Power Output:	74.0 kW (99 bhp)
Open Market Value:	\$24,482.00
Original Registration Date:	26 Dec 2017
First Registration Date:	26 Dec 2017
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$5,000.00 7(2)
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Dec 2027
PARF Rebate Amount: Intended COE Rebate Details	\$3,250.00
COE Expiry Date:	25 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,791.00
COE Rebate Amount:	\$15,395.00
Total Rebate Amount: Message	\$18,645.00
You will not be eligible for any COE rebate from the cu	urrent COE (including unused COE from any lay-up period/s), if you renew your COE

The information contained herein is correct as at 10 Sep 2024



Terms of Service | Privacy | PDPA ©2004-2024 Sgcarmart, Singapore. All rights reserved.

Compare



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road

#08-1339 Singapore 470130

LKK Auto Consultants hence notify Tel: 9450 7920

the Repairer of the following autowerks@gmail.com
To resurvey before/after spray painting
To display damaged part(s) during resurvey
Parts prices are subject to confirmatio 30 September 2024

• Third party survey is on a "Without Prejudice" basis

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

NOF Aulum

REG NO.: **SLV 1899 J** MAKE/MODEL: **TOYOTA PRIUS**

	The shift of Acknowledged b	y Repairer			
ESTIMATED RE	PAIR COST FOR THE VEHICLE MENTIONED ABOVE Signature:				
QTY	DESCRIPTION	OLDER OF STREET, MILES AND	-	AM	T(S\$)
	<u>LIST ITEMS</u>				
1	Rear windscreen moulding / /		\$	21	0.35 V
1	Rear tailgate \wedge		\$	1,49	9.50
1	Rear tailgate lock		\$	23	3.96
1	Rear tailgate rubber		\$	26	6.54
1	Rear tailgate "TOYOTA" emblem 🔥 🔿		\$	4	6.20
1	Rear tailgate "PRIUS" emblem		\$	11	0.21
1	Rear tailgate "HYBRID SYNERGY" emblem < ✓		\$	10	0.54 X
1	Rear taillamp -LH (\sim		\$	820.21 97	7.21
1	Rear end panel		\$	90	0.54 X
1	Rear bumper Ton		\$	PKG-10 1,27	5.40
1	Rear bumper bracket		\$		0.87 X
1	Rear bumper inner sponge		\$		1.21 X
1	Rear bumper lower side garnish \mathcal{N}		\$		5.90 X
1	Rear bumper reflector		\$		5.00 X
1	Rear bumper reinforcement BM€		\$		0.21
2	Rear bumper side retainers Msc/2		\$		1.94 /7 C
1	Rear fender -LH		\$		9.54 X
1	Rear fender inner shield Λ_{Λ}		\$		5.00 ×
			\$	8,810	Name and Address of the Owner, when the Owner, where the Owner, which is the
		Less 25%	\$	2,20	
			\$	6,60	
				,	
	SPECIAL NETT ITEMS				
1	Rear windscreen sealant		\$	80	0.00 X
1	Rear bumper clip (1 set)		\$	80	0.00 30
1	Rear fender inner shield clip (1 set)		\$	60	0.00 ×
			\$	220	0.00
21					
S/N	LABOUR CHARGES				
1	To remove, replaced damaged lamps and check up rear wiring.		\$		0.00 20
2	To remove and refit inner garnishes.		\$		0.00 €2
3	To transfer rear tailgate mechanism and wiring assembly.		\$	01 1).00 ×
4	To remove and refit rear windscreen glass.		\$).00 X
5	To apply undercoating.		\$		0.00 X
6	Panel beating.		\$	1,500	0.00 500
7	To re-spray painting on the affected areas.		\$	1,400	
			\$	3,520	0.00

757AL 810347.59