

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24090155/UMA3Q2
Date: 06/12/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002582_01
Claimant Vehicle No : SKD2001H Insured Vehicle No : SLT8320B
Date of Loss: 07/09/2024 Nature of Claim: TP Claim No: MFL2024D0010725

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKD2001H
Make & Model: MERCEDES-BENZ S350L, 3.5 (A) Engine No: 27296531552121
Reg. Date: 24/09/2010 (Man. Year: 2010) Chassis No: WDD2211562A339625
Colour: Black Odometer: 315374 km
Engine Capacity: 3498 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/45 R18 Rear Tyre Size: 255/45 R18
Front Left Side: Bridgestone 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,908.96	3,359.34	3,549.62	51.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,370.00	720.00	650.00	47.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,278.96	4,079.34	4,199.62	50.73
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	8,278.96	3,200.00	5,078.96	61.35
+ Car Rental (3.0 x S\$120.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		3,587.25		
Global Sum Settlement (S\$)		3,580.00		

INSPECTION

Date of Assignment: 10/09/2024
Date Inspected: 10/09/2024 Inspected At: T K Lee Automotive Pte Ltd (HQ)
Singapore 417883
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Oct 2024)
Parts:	143	MERCEDES-BENZ S350L 3.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD2001H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed / Torn	1,998.63 FN	*1,998.63 FN
2	4		*REAR BUMPER PDC SENSOR	Serviceable	1,255.00 FN	*- FN
3	1		*REAR BUMPER TOP GUIDE	Not Necessary	186.55 FN	*- FN
4	1		*REAR BUMPER LOWER GUIDE	Twisted	160.90 FN	*160.90 FN
5	1		*REAR BUMPER REINFORCEMENT	Bent	817.62 FN	*817.62 FN
6	2		*REAR BUMPER SIDE GUIDE R/L	Not Necessary	220.50 FN	*- FN
7	1		*REAR EXHAUST CHROME TRIMS -R/L	N/S Scratched / Bent	1,560.44 FN	*520.00 FN
8	2		*REAR EXHAUST CHROME TRIM BRACKETS	Not Necessary	310.00 FN	*- FN
9	1		*REAR TAILLAMP LH	Not Necessary	931.53 FN	*- FN
10	2		*REAR BUMPER CHROME MOULDING R/L	Necessary	179.90 FN	*179.90 FN
11	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
						F=Franchise part. S=SpcNett. N=NettItemDisc.
					Sub Total (\$\$)	7,671.07 3,727.05
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	762.11 367.71
					Total Parts (\$\$)	6,908.96 3,359.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE & REFIX INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	0.00
3	TO PUTTY SPRAY PAINT & POLISH AFFECTED PARTS	New	600.00	400.00
4	TO PANEL BEAT ,CUT ,WELD REMOVE & REPLACE DAMAGED PARTS	New	600.00	300.00
Gross Labour Cost (\$\$)			1,370.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >