

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

Our File No: CS/CTI24090156/UVH3M4  
Date: 25/09/2024

REFERENCE

Insured/Claimant: YIN HONGLI Policy No: DMPCSNW00013902403  
Date of Loss: 04/09/2024 Nature of Claim: OD Claim No: SNM24D204995/C01/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKD6339H  
Make & Model: FORD MONDEO, 2.0 ESTATE TITANIUM GTDI SR (A) Engine No: GC87924  
Reg. Date: 28/02/2017 (Man. Year: 2016) Chassis No: WF0FXXWPCFGC87924  
Colour: Grey Odometer: 0 km  
Engine Capacity: 1999 cc  
Market Value/New Car Price: S\$52,000.00  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50R17 Rear Tyre Size: 225/50R17  
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm  
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	0.00	750.00	-750.00	
Nett Amount (S\$)	0.00	-750.00	750.00	

INSPECTION

Date of Assignment: 09/09/2024 Present Location: SME Motor Pte Ltd (Kaki Bukit)  
SME Motor Pte Ltd (Kaki Bukit)  
Date Inspected: 10/09/2024 Inspected At: 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit  
Singapore 417883  
Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

**TOTAL LOSS ASPECT**

Market Value :	\$52,000.00
OMV :	\$28,591.00
PARF Rebate (1) :	\$19,216.00
Quota Premium Paid :	\$50,621.00
COE Rebate (2) :	\$12,489.00
Total Rebate (1) + (2) = :	\$31,705.00

The total amount incurred will be Market Value \$52,000.00 minus Total Rebate \$31,705.00 = \$20,295.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Sep 2024)
Parts:	143	FORD MONDEO 2.0 ESTATE TITANIUM GTDI SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD6339H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**