



Your Ref : SNM24D204995/C01

Date: 25th September 2024

Our Ref : CS/CTI24090156/Uvh3m4

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SKD 6339H
ACCIDENT ON 04/09/2024**

Instruction was received to inspect the vehicle Reg. No. SKD 6339H. The inspection was conducted on 10/09/2024 at the premises of M/s SME Motor Pte Ltd, 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883.

The following vehicle information was recorded:

Registration Number	: SKD 6339H
Make/Model	: Ford Mondeo Estate Titanium 2.0 AT GTDI SR
Year of Registration	: 2017
Body Colour	: Grey
Chassis Number	: WF0FXXWPCFGC87924
Engine Capacity	: 1999 cc
Speedometer Reading	: N/A

The vehicle caught fire. The cause of fire probably due to electrical short circuit. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$	52,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$	31,705.00)
Nett Liability	S\$	20,295.00
	=====	

Vehicle Inspected By:



MUHD NAZRIL (NAZ)
Technical Investigator
LL.B. (Hons) London



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.