

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	SLT425K_130624
Policy No:	MPC23B00O80400	Date of Loss:	13/06/2024
Vehicle Reg. No.:	SLT425K	Driveable?	
Driver Age/Info:	35	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	FOK YAN HO	Contact No:	+6592749725
Driver:	FOK YAN HO		
Make/Model:	KIA CERATO, 1.6 (A)	Vehicle Reg. Date:	16/10/2017
Vehicle Colour:	GREY	Chassis No:	KNAFX411MJ5747136
Engine No:	G4FGHH682294		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	DICKSON AUTO CARE CENTRE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	1,706.10
Miscellaneous Items	0.00
Labour	1,260.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,966.10
+ GST 9.00% (S\$)	266.95
Nett Amount (S\$)	3,233.05

This claim is handled by: POON HENG CHEONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Print Code: (Unsubmitted, no print-code for SL1425K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	REPAIR	Bonnet X R	0.00	0.00	-
2	1		Bumper alr grille center, front / BR	0.00	0.00	*165.00 F /
3	1		Bumper reinforcement, front ? x nn	0.00	0.00	*185.00 F
4	1		Bumper, front / B.R	0.00	0.00	*260.00 F /
5	1		Fender RH, front X R	0.00	0.00	*110.00 F
6	1		Headlamp RH / CUT	0.00	0.00	*650.00 F /
7	1		Number plate bracket LH, front X nn	0.00	0.00	*45.00 F
8	1		*FRONT BUMPER TOWING COVER / CR4	0.00	0.00	*8.00 F /
9	1		*FRONT BUMPER CLIPS / MC	0.00	0.00	*15.00 F /
10	1		*FRONT BUMPER SPONGE / x nn	0.00	0.00	*45.00 F
11	1		*FRONT BUMPER SIDE RETAINER LH & RH / BR	0.00	0.00	*20.00 F /
12	1		*FRONT BUMPER LOGO / MC	0.00	0.00	*25.00 F /
13	1		*FRONT BONNET - REPAIR X R	0.00	0.00	-
14	1		Number plate garnish, rear X nn	0.00	0.00	*23.00 F

F=Franchise part.

Sub Total (\$\$)	1,551.00
+ Margin on L,N Items 10.00% (\$\$)	155.10
Total Parts (\$\$)	1,706.10

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

1143.00
+10%
1257.30

Our Items

TO REMOVE & REFIT FRONT HEADLAMP & REFOCUS	New	30	60.00
TO PROVIDE LABOUR TO REMOVE ALL DAMAGED PARTS & PANELS	New	300	600.00
3 TO PROVIDE LABOUR & MATERIAL TO PAINT NEW PARTS & PANELS	New		600.00 ✓
Gross Labour Cost (S\$)			1,260.00 930

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Stew (LKK)

27/6/24, 10:30CL

2187.30

~~PA~~ 90-AL AL

L/S - 1749.84
= 1750

Excess - ?

L/S

4 AL sm
3 dys

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: