

LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

To: INDIA INTERNATIONAL INSURANCE PL
64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: LOGANATHAN S/O AGORAM

Date: 03/10/2024

PRELIMINARY ADVICE

Vehicle No	SKT 9876U	Accident Date	10/09/2024
Make	BMW X1 SDRIVE18I 1.5 LED NAV	Policy No.	D23MFL0002571_01
Assignment Date	10/09/2024	Excess	-
Inspection Date	23/9/2024	Est. Duration of Repair	3 days

Inspected At: Performance Motors Limited

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Workshop Estimate Amount:	\$6,195.70
Revised Estimate Amount:	\$3,781.15
"Check" Items Amount	\$1,948.70
Total	\$5,729.85

Total Loss Consideration

Book Value	\$0.00
Market Value	\$0.00
COE / PARF Rebate	
Salvage Value	\$0.00
Margin for Repair	

Remarks

- [] The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- [] The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- [] Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.