

Dealer
Performance Motors Limited
A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

10 Sept 2024

Estimate No. : b1 71134
Date Estimated : 10/09/2024
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

May Ng
616 WOODLANDS AVENUE 4
12- 559

SINGAPORE 730616

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT9876U	WBAJG12000EN52844	26/06/2019	X1 sDrive18i	92582

DESCRIPTION

Replace rear bumper include remove attachment etc and carryout necessary repairing work on accident damage area

VALUE
850 1,275.00

Painting rear bumper

1,038.00

To check electrical wiring system and lighting at the rear section for proper function.

177.00

Sundries.

80? 150.00

Total Labour 1: **2,640.00**

DESCRIPTION

RR BUMPER CARRIER *? Xan*
MOUNTING SMART OPENER *? Xan*
REAR TRIM UNDERRIDE PROTECTION (X L *sun* /
Abrasion gua *? X11*
Abrasion gua *? Xan*
REAR BUMPER PANEL PRIMED *de* /
REAR BUMPER MIDDLE TRIM PANEL (PDC) *sun* /
REAR BUMPER TRIM BOTTOM (LINES) *sun* /
REAR BUMPER TOWING EYE COVER *Xan*
CLIP *? Xan*
ULTRASONIC SENSOR BLACK *? Xan*
DECOUPING RING PDC TORQUE CONVERTER *? Xan*

QTY	PRIC	VALUE
1	561.20	561.20
1	86.70	86.70
1	168.75	168.75
1	2.90	2.90
1	2.90	2.90
1	964.30	964.30
1	283.55	283.55
1	299.55	299.55
1	40.85	40.85
26	1.25	32.50
4	269.65	1,078.60
6	5.65	33.90

Total Parts : **3,555.70**



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 71134
Date Estimated : 10/09/2024
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT9876U	WBAJG12000EN52844	26/06/2019	X1 sDrive18i	92582

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 23/09/24 Excess S\$ _____

Surveyor's Name RASUL Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 3 day

Reg 14 paint

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____



Labour 1	:	2,640.00
Parts	:	3,555.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	557.61
Grand Total	:	6,753.31

Performance Motors

BMW Dealer



Final Report

Estimate No. : b1 71134
Date Estimated : 10/09/2024
Prepared By : Chua Kee Sin

Page No. :

- ESTIMATE REPAIR FOR -

May Ng
616 WOODLANDS AVENUE 4
12- 559

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

SINGAPORE 730616

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SKT9876U	WBAJG12000EN52844	26/06/2019	X1 sDrive18i	92582

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper panel, rear middle trim panel, rear trim bottom, rear trim underride protection include carrying out other necessary repairs caused by the accident	850.00		850.00
To spray paint rear bumper	1,038.00		1,038.00
To check electrical wiring system and lightings at the rear section for proper function	177.00		177.00
To remove PDC assembly, replace damaged parts include reconnecting to bumper and conducting checks for proper function	177.00		177.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR TRIM UNDERRIDE PROTECTION (X L	168.75	1.00	0.00	168.75
REAR BUMPER PANEL PRIMED	964.30	1.00	0.00	964.30
REAR BUMPER MIDDLE TRIM PANEL (PDC)	283.55	1.00	0.00	283.55
REAR BUMPER TRIM BOTTOM (LINES)	299.55	1.00	0.00	299.55
# EXPANDING RIVET BLACK	1.50	10.00	0.00	15.00

SUPPLEMENTARY ITEMS

Total Labour :	2,322.00
Total Parts :	1,731.15
Total Labour & Parts (before GST) :	4,053.15
Deduction for Excess :	
Total Repair Costs less Excess:	4,053.15
GST @9%:	364.78
Grand Total :	4,417.93

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

A Sime Darby Motors Company

Performance Motors

BMW Dealer



Supplementary

Estimate No. : b1 71134
Date Estimated : 10/09/2024
Prepared By : Chua Kee Sin

Page No. :

- ESTIMATE REPAIR FOR -

May Ng

616 WOODLANDS AVENUE 4

12- 559

SINGAPORE 730616

- ACCOUNT - 219

India Int'L Insurance Pte Ltd

64 Cecil Street

#04-05 IOB Building

Singapore 049711

REGN. NO.	CHASSI S NO.	REGN. DATE	MODEL	M LEASE
SKT9876U	WBAJG12000EN52844	26/06/2019	X1 sDrive18i	92582

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# EXPANDING RIVET BLACK	1.50	10.00	0.00	15.00
-------------------------	------	-------	------	-------

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	15.00
Total Labour & Parts (before GST) :	15.00

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

A Sime Darby Motors Company