

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

Veron.

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00
 Springleaf Tower
 Singapore 079909
 Tel : 6389 - 6111
 Fax : 6224 - 7478 / 7175

Quotation

DATE : 12.09.2024
 VEH NO : SDJ3389J
 MODEL : Toyota Estima
 D O A : 07.09.2024
 YR REF : PD890L

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SDJ3389J (TOYOTA ESTIMA)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Deband</i>	1	895.90 ✓
2	Rear Bumper Side Holder <i>new</i>	1	85.90 +
3	Rear Bumper Side Sponge	1	137.80 +
4	Rear Bumper Reflector <i>crackd</i>	1	67.10 ✓
5	Rear Bumper Tow Cover <i>Deband</i>	1	47.10 ✓
6	Rear End Panel <i>Repr</i>	1	755.90 +
7	Rear End Panel Top Garnish <i>Deband</i>	1	249.10 ✓
8	Rear End Panel Lower Garnish <i>new</i>	1	139.60 ✓
9	Rear End Panel Antenna Sensor	1	195.60 +
10	Rear End Panel Buzzer <i>new</i>	1	155.80 +
11	Taillamp <i>crackd</i>	1	606.90 ✓
12	Taillamp Panel <i>Repr</i>	1	369.50 +
13	Tailgate <i>Dented</i>	1	1,858.30 ✓
14	Tailgate Lock <i>new</i>	1	590.60 ✓
15	Tailgate Lock Cover <i>new</i>	1	55.90 +
16	Tailgate Weatherstripe <i>cut</i>	1	311.70 ✓
17	Tailgate Inner Trimboard <i>new</i>	1	695.30 +
18	Tailgate Auto Lock Side Sensor <i>new</i>	1	499.90 ✓
19	Tailgate Reflector <i>crackd</i>	1	388.80 ✓
20	Tailgate Glass Moulding <i>new</i>	1	156.30 ✓
21	Toyota Logo	1	85.90 ✓
22	Estima Wording <i>new</i>	1	74.20 ✓
23	Areas Wording	1	70.30 ✓
24	Rear Fender <i>Dented</i>	1	1,150.20 ✓
25	Rear Fender Inner Trimboard <i>Deband</i>	1	937.20 ✓
26	Rear Fender Inner Shield <i>new</i>	1	141.30 X
27	Floor Panel Top Cover <i>new</i>	1	687.20 +
28	Front Bumper <i>Deband</i>	1	960.20 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR SDJ3389J (TOYOTA ESTIMA)

29	Front Bumper Side Holder - LH & RH <i>new</i>	2	159.20	+
30	Front Bumper Reinforcement <i>Dented</i>	1	388.90	✓
31	Front Bumper Sponge <i>crushed</i>	1	195.20	✓
32	Front Bumper Lower Grille <i>behind</i>	1	465.10	✓
33	Front Bumper Lower Grille Chrome Trim <i>crushed</i>	1	225.30	✓
34	Front Bumper Tow Cover	1	55.20	x
35	Front Bumper Fog Lamp <i>new</i>	2	640.40	x
36	Front Bumper Fog Lamp Cover	2	371.80	+
37	Radiator Grille <i>new</i>	1	587.30	+
38	Radiator Grille Logo	1	89.60	+
39	Headlamp (HID) <i>RH crushed</i>	2	6,392.60	3196.30
40	Air Con Condenser <i>new</i>	1	1,696.90	x
			\$	23,637.00
			\$	(5,909.25)
			\$	17,727.75

13420.50
10065.37
Less 25%

S/NETT ITEMS

1	Rear Bumper Clips <i>new</i>	1 set	50.00	✓
2	Reverse Sensor <i>Dented</i>	1 set	280.00 200	
3	Rear End Panel Top Garnish Clips <i>new</i>	1 set	20.00	✓
4	Rear End Panel Lower Garnish Clips <i>new</i>	1 set	20.00	+
5	Rear End Panel Sealant <i>new</i>	1	60.00	x
6	Tailgate Inner Trimboard Clips <i>new</i>	1 set	30.00	+
7	Tailgate Auto Lock Side Sensor Clips <i>new</i>	1 set	20.00	✓
8	Tailgate Glass Sealant <i>new</i>	1	60.00	✓
9	Rear Fender Sealant <i>new</i>	1	60.00	✓
10	Rear Fender Glass Sealant <i>new</i>	1	50.00	✓
11	Front Number Plate <i>crushed</i>	1	30.00	✓
12	Front Number Plate Holder <i>behind</i>	1	30.00	✓
13	Front Bumper Clips <i>new</i>	1 set	50.00	✓
14	Front Bumper Sensor <i>Damaged</i>	1	280.00 200	
Total parts			\$	18,767.75

770

LABOUR CHARGE

1	To knocking out front & rear portion & renew above parts	\$	2,000.00 1200
2	To putty & spray up paint works	\$	1,800.00 1000
3	To check wiring	\$	100.00 60
4	To apply tuff coat	\$	180.00 80
5	To remove front bumper sensor	\$	100.00 50
6	To remove air con condenser & top-up gas	\$	120.00 x

RE : ESTIMATE FOR ACCIDENT REPAIR SDJ3389J (TOYOTA ESTIMA)

7	To remove upholstery	\$	150.00	80
8	To remove reverse sensor	\$	100.00	50
9	To remove rear camera	\$	100.00	50
10	To remove rear video recorder	\$	100.00	50
11	To transfer tailgate fittings	\$	150.00	80
12	To remove rear fender glass	\$	100.00	50
13	To remove tailgate glass	\$	180.00	120
			2870	
Total Labour		\$	5,180.00	
Grand Total		\$	23,947.75	

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 13705.37
L/S: 10950

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: