

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURAN	ICE LTD	Ref:	CS/INC24090162/Aqh3m4	
	75 BRAS BASAH R	OAD SINGAPORE 189557	Date:	26/11/2024	
	INCOME CENTRE	SINGAPORE 109557	Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SML 1710K	Veh. Inspected	SNP 6886X (SKG 9381Z)	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1294418-002	Excess	\$0.00	
	Assign From	HELENA TAN	Assign Date	10/09/2024	
2. Vehicle Details					
	Make & Model	TOYOTA LEXUS IS250C	c.c	2500	
	Engine No.	4GR0794020	Year of Reg.	26/03/2012	
	Chassis No.	JTHFK252102523198	Colour	BLUE	
	Odometer	170493 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	235/40R18	PIRELLI	6	
	L/H Front Tyre	235/40R18	PIRELLI	6	
	R/H Rear Tyre	235/40R18	PIRELLI	6	
	L/H Rear Tyre	235/40R18	PIRELLI	6	
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	06/09/2024	Inspection Date	10/09/2024 (13:12)	
	Survey held at	N-51 AUTOMOTIVE PL			
		2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB			
		SINGAPORE 417921			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.					
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					