



Company & GST Registration No. 200616038C

2 Kaki Bukit Avenue 2 #01-17/#01-18 /Heavy Vehicle #01-08/Spray Painting #02-27

Kaki Bukit Autohub Singapore 417921

Tel: 68420051 Fax: 67410510

Email: sales@n51.com.sg

DEREK CHANG JIAN HUA

8 SELEGIE ROAD

#04-09

SINGAPORE 180008

Repair Code: CLM18369

Date in: 09/09/2024

Vehicle No.: SKG9318Z (SNP6886X)

Model: TOYOTA LEXUS IS250C AUTO STD

Chassis/Eng#: JTHFK252102523198/4GR0794020

SUPPLEMENTARY ITEMS

No	Description Of Parts	Qty	Unit Price	Amount
1	REAR RH FENDER MUDFLAP <i>Built</i>	L	1	\$ 140.60
2	REAR BUMPER RH LOWER BRACKET <i>2nd</i>	L	1	\$ 102.30
Sub total before discount:				\$ 242.90
Percentage discount 10%:				\$ 24.29
Sub-total 1 :				\$ 218.61
Parts Total:				\$ 218.61

Adrian
2/5 10/09/24.
Supplementary: 218.61