

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CHIA BOON WAH
26 TOSCA TERRACE
SINGAPORE 455420

Contact : 97441203

TAX INVOICE

TP INC
Xiao Chen

Repair Code : CLM18174

Date in : 05/09/2024

Vehicle Num. : SMR3196A

Model : HYUNDAI I30 PDE 1.4 WAGON T-GDI DCT

Chassis/Eng# : TMAH3813VLJ068565/G4LDKG035042

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dented</i>	1	805.00	✓ 805.00
REAR BUMPER LOWER LID <i>Dented</i>	1	380.00	✓ 380.00
REAR BUMPER REFLECTOR L/R <i>new</i>	2	80.00	+ 160.00
REAR BUMPER REINFORCEMENT <i>new</i>	1	435.00	+ 435.00
REAR BUMPER REINFORCEMENT BRACKET L/R <i>Dented</i>	2	178.00	✓ 356.00
REAR BUMPER REVERSE SENSOR <i>2 pieces dented</i>	4	175.00	350 700.00
REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	4	20.00	✓ 80.00
REAR BUMPER TOW HOOK COVER <i>new</i>	1	28.00	+ 28.00
REAR END PANEL <i>Dented</i>	1	1321.00	985 1,321.00
REAR END PANEL ANTENNA SENSOR <i>new</i>	1	65.00	✓ 65.00
REAR END PANEL INNER TOP GARNISH <i>Dented</i>	1	225.00	✓ 225.00
REAR FLOOR PANEL COMPARTMENT TRAY <i>new</i>	1	835.00	398 835.00
REAR FLOOR PANEL TOP BOARD COVER <i>new</i>	1	465.00	✓ 465.00
REAR TAILGATE <i>Dented</i>	1	2295.00	1689 2,295.00
REAR TAILGATE '1.4 T' EMBLEM	1	40.00	✓ 40.00
REAR TAILGATE 'I30' EMBLEM	1	45.00	✓ 45.00
REAR TAILGATE 'LOGO' EMBLEM	1	55.00	✓ 55.00
REAR TAILGATE 'LOGO' EMBLEM BASE <i>new</i>	1	65.00	✓ 65.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

CHIA BOON WAH
 26 TOSCA TERRACE
 SINGAPORE 455420

Contact : 97441203

TAX INVOICE

Repair Code : CLM18174

Date in : 05/09/2024

Vehicle Num. : SMR3196A

Model : HYUNDAI I30 PDE 1.4 WAGON T-GDI DCT

Chassis/Eng# : TMAH3813VLJ068565/G4LDKG035042

REAR TAILGATE HINGES L/R	2	55.00	+	110.00
REAR TAILGATE INNER RUBBER STOPPER L/R	2	18.00	+	36.00
REAR TAILGATE INNER TRIM BOARD	1	445.00	✓	445.00
REAR TAILGATE MECHANISM LOCK	1	165.00	✓	165.00
REAR TAILGATE NUMBER PLATE LAMP L/R	2	135.00	+	270.00
REAR TAILGATE OUTER LOCK SWITCH WITH CAMERA	1	830.00	+	830.00
REAR TAILGATE REFLECTOR L/R	2	82.00	+	164.00
REAR TAILGATE REFLECTOR LAMP L/R	2	795.00	+	1,590.00
REAR TAILGATE WEATHER STRIP	1	288.00	✓	288.00
REAR TAILGATE WINDSCREEN MOULDING - SET	1	80.00	✓	80.00

Subtotal before discount

12,333.00

Percentage discount 20%

2,466.60

Sub-total 1

9,866.40

REAR BUMPER CLIPS - SET	1	80.00	30	80.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	50.00	20	50.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	50.00	30	50.00
REAR TAILGATE NUMBER PLATE	1	25.00	✓	25.00
REAR TAILGATE NUMBER PLATE HOLDER	1	50.00	30	50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

CHIA BOON WAH
 26 TOSCA TERRACE
 SINGAPORE 455420

Contact : 97441203

TAX INVOICE

Repair Code : CLM18174
 Date in : 05/09/2024
 Vehicle Num. : SMR3196A
 Model : HYUNDAI I30 PDE 1.4 WAGON T-GDI DCT
 Chassis/Eng# : TMAH3813VLJ068565/G4LDKG035042

REAR TAILGATE WINDSCREEN SEALANT	1	80.00	80.00
Subtotal before discount			335.00
Percentage discount 0%			0.00
Sub-total 2			335.00
Parts-total			10,201.40

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	80.00
To remove, reinstall tailgate windscreen	120 150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60 100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	700 1,100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1880 800 1,000.00
To apply anti-rust chemical on repaired and replaced panel.	60 120.00
To remove, reinstall tailgate mechanism and check for function	60 80.00
Labour Total	2,630.00
Parts & Labour Total	12,831.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

*** This is a computer-generated document which requires no signature. ***

No illegal modification(s) is allowed on a "without prejudice" basis

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian
 2/5 10/09/24
 06295
 total: 8056.60
 4/5: 641K
 6.41K