

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TPWC
VERON

XIANG YANXIA
3 LORONG 42 GEYLANG #06-11
SINGAPORE 398026

TAX INVOICE

Repair Code : CLM18367

Date in : 09/09/2024

Vehicle Num. : SLR5449U

Model : TOYOTA LEXUS RX400H HYBRID

Chassis/Eng# : JTJHW31U602858434/3MZ0602825

Contact : 97210867 96366567

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
ENGINE OIL SUMP <i>Dented</i>	1	371.30	371.30
FRONT BUMPER <i>Delud</i>	1	1643.50	1,643.50
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	125.30	+ 250.60
FRONT BUMPER SPONGE <i>new</i>	1	431.10	+ 431.10
FRONT BUMPER TOW HOOK COVER <i>new</i>	1	27.90	+ 27.90
FRONT BUMPER UNDER COVER (CENTER) <i>new</i>	1	264.80	264.80
FRONT RH FENDER INNER SHIELD <i>new</i>	1	483.60	483.60
FRONT WASHER TANK <i>Delud</i>	1	462.20	462.20
FRONT WASHER TANK MOTOR <i>new</i>	1	310.60	+ 310.60
REAR BUMPER <i>new</i>	1	1643.50	+ 1,643.50
ROCKER GARNISH RH <i>Delud</i>	1	1213.70	1,213.70
Subtotal before discount			7,102.80
Percentage discount 10%			710.28
Sub-total 1			6,392.52
ENGINE OIL <i>new</i>	1	100.00	100.00
FRONT BUMPER CLIPS - SET <i>new</i>	1	80.00	80.00
FRONT RH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	50.00	50.00
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

XIANG YANXIA
3 LORONG 42 GEYLANG #06-11
SINGAPORE 398026

Contact : 97210867 96366567

TAX INVOICE

Repair Code : CLM18367

Date in : 09/09/2024

Vehicle Num. : SLR5449U

Model : TOYOTA LEXUS RX400H HYBRID

Chassis/Eng# : JTJHW31U602858434/3MZ0602825

ROCKER GARNISH RH CLIPS - SET	1	50.00	30 50.00
	Subtotal before discount		360.00
Percentage discount 0%			0.00
	Sub-total 2		360.00
	Parts-total		6,752.52

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To remove, install engine with transmission. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

	80.00
	100.00
	1,000.00
	800.00
	120.00
Labour Total	2,100.00
Parts & Labour Total	8,852.52

*** This is a computer-generated document which requires no signature.***

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

page 2

Adrian L
2/s 10/09/24
04 Ryn.

total: 4279.12
4/s: 3.41K
3.41K