



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2505855

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581
ATTN: KON YIN SIEW

INV Date 01/09/2025
Reference CD/FCI24090165/Rpa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SFJ 2992A
Insured Veh. SHA 4751P
Claim No. D24007783MFCT/CTPL/TPD-2
Policy No. D-24101861MFCT
Accident Date 03/09/2024
Inspection Date 11/11/2024

Description	Total
Third Party Express Settlement	300.00
Subtotal	300.00
GST (9%)	27.00
Grand Total	327.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: KON YIN SIEW			Ref: CD/FCI24090165/Rpa3q2(N) Date: 01/09/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4751P	Veh. Inspected	SFJ 2992A	
Policy No.	D-24101861MFCT	Coverage (\$)	0.00	
Claim No.	D24007783MFCT/CTPL/TPD-2	Excess (\$)	0.00	
Assign From	KON YIN SIEW	Assign Date	11/11/2024	
2. Vehicle Particulars & Condition				
Make & Model	PEUGEOT 5008 ACTIVE PURETECH 1.2	c.c	1199	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	VF3MRHNYWHL075975	Colour	GREY	
Odometer	103296 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/65 R17	PIRELLI	6 mm	
L/H Front Tyre	215/65 R17	PIRELLI	6 mm	
R/H Rear Tyre	215/65 R17	PIRELLI	6 mm	
L/H Rear Tyre	215/65 R17	PIRELLI	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	03/09/2024	Inspection Date	11/11/2024	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFJ 2992A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	SCRATCHED	1,490.00	1,490.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	780.00	-
2	REVERSE SENSOR INNER LH & RH @\$250.00	NOT NECESSARY	500.00	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	130.00	-
2	REVERSE SENSOR INNER BRKT RH & LH (NPA)	NOT NECESSARY	-	-
1	TAILGATE (NPA)	TO REPAIR SEE LABOUR	-	-
1	TAILGATE EMBLEM 5008	NECESSARY	130.00	130.00
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-303.00	-162.00
			2,727.00	1,458.00
	<u>LABOUR</u>			
	TO CUT WELD ,PANEL BEAT ,STRAIGHTEN ,REPLACE DAMAGED PARTS & REALIGN AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF TAILGATE AND REAR END PANEL .		700.00	400.00
	TO PUTTY SPRAY PAINT ON TAILGATE ,REAR END PANEL ,REAR BUMPER REINFORCEMENT .		600.00	200.00
	TO APPLY SPRAY TEROSTAT SEALANT ON REAR END PANEL.	NOT NECESSARY	100.00	-
	TO CHECK ELECTRICAL & WIRING SYSTEM FOR PROPER FUNCTION.	NOT NECESSARY	100.00	-
	TO RESET & REPROGRAMMING AFTER ACCIDENT REPAIR WORK.		280.00	150.00
			1,780.00	750.00
GRAND TOTAL			4,507.00	2,208.00
RECOMMENDED COST OF REPAIRS				2,208.00

Report Ref No. CD/FCI24090165/Rpa3q2(N)

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SFJ 2992A



PHOTOGRAPHS FOR VEHICLE NO. : SFJ 2992A





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 3 of 10)

PHOTOGRAPHS FOR VEHICLE NO. : SFJ 2992A



PHOTOGRAPHS FOR VEHICLE NO. : SFJ 2992A



PHOTOGRAPHS FOR VEHICLE NO. : SFJ 2992A



PHOTOGRAPHS FOR VEHICLE NO. : SFJ 2992A



PHOTOGRAPHS FOR VEHICLE NO. : SFJ 2992A



PHOTOGRAPHS FOR VEHICLE NO. : SFJ 2992A





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 9 of 10)

PHOTOGRAPHS FOR VEHICLE NO. : SFJ 2992A





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 10 of 10)

PHOTOGRAPHS FOR VEHICLE NO. : SFJ 2992A



PHOTOGRAPHS FOR VEHICLE NO. : SFJ 2992A





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SFJ 2992A

