

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200714616M  
 GST Registration No. : 200714616M

TP/INC  
 VERON.

## TAX INVOICE

ROSET LIMOUSINE SERVICES PTE LTD  
 53 UBI AVE 1 #03-47 PAYA UBI IND PARK  
 SINGAPORE 408934

Repair Code : CLM16418

Date in : 09/09/2024

Vehicle Num. : SLP7250Y

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31218308/LEB5918319

Contact : 87420435 89028482

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BODY EXTENSION LH <i>Repr</i>	1	720.00	+ 720.00
REAR BODY EXTENSION UPPER PANEL LH <i>Repr Distorted</i>	1	160.00	✓ 160.00
REAR BUMPER <i>Distorted</i>	1	762.70	✓ 762.70
REAR BUMPER LOWER COVER <i>Delhd</i>	1	250.00	✓ 250.00
REAR BUMPER REFLECTOR L/R <i>LH → LH cancelled</i>	2	141.10	282.20
REAR BUMPER SIDE L/R <i>LH Delhd</i>	2	195.00	195 390.00
REAR BUMPER SIDE RETAINER L/R <i>New</i>	2	23.00	+ 46.00
REAR END PANEL <i>Delhd</i>	1	415.60	✓ 415.60
REAR END PANEL INNER TOP GARNISH <i>Delhd</i>	1	98.00	✓ 98.00
REAR FLOOR PANEL <i>Repr</i>	1	662.20	+ 662.20
REAR FLOOR PANEL COMPARTMENT TRAY GARNISH <i>cancel</i>	1	485.30	✓ 485.30
REAR FLOOR PANEL INNER TOP BOARD COVER <i>cancel</i>	1	430.30	✓ 430.30
REAR LH FENDER <i>Repr Buckled</i>	1	790.20	✓ 790.20
REAR LH FENDER ARCH GARNISH <i>Delhd</i>	1	195.00	✓ 195.00
REAR LH FENDER INNER AIR VENT <i>Delhd</i>	1	30.30	✓ 30.30
REAR LH FENDER INNER PANEL <i>Repr</i>	1	505.00	+ 505.00
REAR LH FENDER INNER SHIELD <i>cancel</i>	1	147.50	✓ 147.50
X REAR LH FENDER INNER TOP GARNISH <i>New</i>	1	392.40	✓ 392.40

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 1

Rear end panel antenna sensor *New* \$ 92.00 X

Rear end panel buzzer sensor \$ 85.00 ✓

cancel

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200714616M  
 GST Registration No. : 200714616M

ROSET LIMOUSINE SERVICES PTE LTD  
 53 UBI AVE 1 #03-47 PAYA UBI IND PARK  
 SINGAPORE 408934

**TAX INVOICE**

Repair Code : CLM16418

Date in : 09/09/2024

Vehicle Num. : SLP7250Y

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31218308/LEB5918319

Contact : 87420435 89028482

REAR LH FENDER INNER TRIM GARNISH	<i>could</i>	1	295.00	<i>✓</i>	295.00
REAR LH FENDER INNER WHEEL HOUSING	<i>Rgr</i>	1	429.80	<i>+</i>	429.80
REAR LH TAILLAMP INNER PANEL	<i>gone</i>	1	278.00	<i>+</i>	278.00
REAR LH TAILLAMP INNER VERTICAL PANEL		1	79.20	<i>+</i>	79.20
REAR TAILGATE	<i>Dented</i>	1	953.30	<i>✓</i>	953.30
REAR TAILGATE 'HYBRID' EMBLEM	<i>new</i>	1	75.80	<i>✓</i>	75.80
REAR TAILGATE 'VEZEL' EMBLEM	<i>new</i>	1	56.20	<i>✓</i>	56.20
REAR TAILGATE DAMPER L/R	<i>gone</i>	2	180.00	<i>+</i>	360.00
REAR TAILGATE HINGES L/R	<i>gone</i>	2	50.00	<i>+</i>	100.00
REAR TAILGATE INNER PULL GARNISH	<i>new</i>	1	27.50	<i>+</i>	27.50
REAR TAILGATE INNER TRIM GARNISH	<i>could</i>	1	153.40	<i>✓</i>	153.40
REAR TAILGATE MECHANISM LOCK	<i>could</i>	1	180.00	<i>✓</i>	180.00
REAR TAILGATE MECHANISM LOCK STRIKER	<i>new</i>	1	27.50	<i>+</i>	27.50
REAR TAILGATE OUTER GARNISH	<i>new</i>	1	220.00	<i>+</i>	220.00
REAR TAILGATE OUTER GARNISH 'H' LOGO EMBLEM	<i>new</i>	1	25.00	<i>+</i>	25.00
REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R	<i>new</i>	2	38.50	<i>+</i>	77.00
REAR TAILGATE REFLECTOR L/R	<i>2H Cut</i>	2	413.20	<i>+</i>	826.40
REAR TAILGATE RUBBER GUIDE STOPPER L/R	<i>new</i>	2	18.50	<i>+</i>	37.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200714616M  
 GST Registration No. : 200714616M

ROSET LIMOUSINE SERVICES PTE LTD  
 53 UBI AVE 1 #03-47 PAYA UBI IND PARK  
 SINGAPORE 408934

**TAX INVOICE**

Repair Code : CLM16418

Date in : 09/09/2024

Vehicle Num. : SLP7250Y

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31218308/LEB5918319

Contact : 87420435 89028482

REAR TAILGATE WINDSCREEN SEALANT <i>NW</i>	<i>420</i>	1	60.00	✓	60.00
REAR TAILLAMP CLIPS L/R - SET <i>He n</i>		2	30.00	✓	60.00
Subtotal before discount					815.00
Percentage discount 0%					0.00
<b>Sub-total 2</b>					<b>815.00</b>
<b>Parts-total</b>					<b>10,582.84</b>

**LABOUR**

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.				✓	80.00
To remove, reinstall tailgate windscreen			<i>120</i>		150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)			<i>60</i>		80.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	<i>2380</i>		<i>900</i>		1200.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.			<i>1100</i>		1400.00
To apply anti-rust chemical on repaired and replaced panel.			<i>60</i>		120.00
To remove, reinstall tailgate mechanism and check for function			<i>60</i>		80.00
<b>Labour Total</b>					<b>3,110.00</b>
<b>Parts &amp; Labour Total</b>					<b>13,692.84</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 4

*Adrian L*  
*2/8 10/09/24*  
*067 rgs*  
*8403.44*  
*total: 8643.92*  
*L/S: 67K 67K ✓*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200714616M  
 GST Registration No. : 200714616M

ROSET LIMOUSINE SERVICES PTE LTD  
 53 UBI AVE 1 #03-47 PAYA UBI IND PARK  
 SINGAPORE 408934

**TAX INVOICE**

Repair Code : CLM16418

Date in : 09/09/2024

Vehicle Num. : SLP7250Y

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31218308/LEB5918319

Contact : 87420435 89028482

REAR TAILGATE WEATHER STRIP	from	1	7004.30	96.80	✓	96.80
REAR TAILGATE WINDSCREEN INNER SEAL	3 per	2	<del>7304.90</del>	50.00	60	100.00
REAR TAILGATE WINDSCREEN MOULDING		2	<del>5843.92</del>	50.00	60	100.00
REAR TAILLAMP L/R	LH Rt	2		474.60	474.60	949.20
Subtotal before discount						12,209.80
Percentage discount 20%						2,441.96
<b>Sub-total 1</b>						<b>9,767.84</b>
REAR BUMPER CLIPS - SET	new	1		50.00	30	50.00
REAR BUMPER REVERSE SENSOR - SET	Repl	1		280.00	200	280.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	new	1		30.00	20	30.00
REAR LH FENDER ARCH GARNISH CLIPS - SET	new	1		40.00	20	40.00
REAR LH FENDER INNER SHIELD CLIPS - SET	new	1		50.00	30	50.00
REAR LH FENDER INNER TRIM GARNISH CLIPS - SET	new	1		30.00	2	30.00
REAR NUMBER PLATE	new	1		25.00	+	25.00
REAR NUMBER PLATE HOLDER	new	1		50.00	+	50.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	new	1		50.00	30	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	new	1		40.00	+	40.00
REAR TAILGATE SPOILER CLIPS - SET	new	1		50.00	+	50.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*