

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SG 1010C				
REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	RHS WHEELARC PANEL	BENT	\$5,916.91	\$4,357.40
1	FUEL COVER	SERVICEABLE	\$800.00	\$0.00
1	GO AHEAD SINGAPORE STICKER	NECESSARY	\$100.00	\$100.00
1	ADBLUE STICKER	NECESSARY	\$30.00	\$30.00
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$448.74)
			\$6,846.91	\$4,038.66
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	LOT ADVERTISMENT (SN)	NECESSARY	\$1,000.00	\$500.00
			\$1,000.00	\$500.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	SUPPLY SKILLED LABOUR TO REPLACE - FRONT RHS WHEELARC WITH SEALANT		\$1,000.00	\$300.00
	SUPPLY SKILLED LABOUR TO REPAIR - FRONT RHS BUMPER, RHS SQUARE BODY PANEL		\$2,000.00	\$300.00
	SUPPLY SKILLED PAINTER & PAINT MATERIAL TO - FRONT RHS WHEELARC, FRONT RHS BUMPER, RHS SQUARE BODY PANEL		\$800.00	\$600.00
			\$3,800.00	\$1,200.00
GRAND TOTAL			\$11,646.91	\$5,738.66
RECOMMENDED COST OF REPAIRS				\$5,738.66

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

Report Ref No: CS/FCI24090169/Rvp3m4