



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24090169/Rvp3m4
16 RAFFLES QUAY	Date:	03/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 3483P	Veh. Inspected	SG 1010C
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24007895MFCT	Excess	\$0.00
Assign From	BETTY	Assign Date	10/09/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ CITARO	C.C	6374
Engine No.	902926C1097535	Year of Reg.	01/12/2015
Chassis No.	WEB62808323129407	Colour	GREEN
Odometer	590450 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	275/70R22.5	FIRENZA	8
L/H Front Tyre	275/70R22.5	FIRENZA	8
R/H Rear Tyre	275/70R22.5 (D)	FIRENZA	8/8
L/H Rear Tyre	275/70R22.5 (D)	FIRENZA	8/8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/09/2024	Inspection Date	10/09/2024
Survey held at	LEXBUILD INTERNATIONAL PTE LTD - 11 TUAS BAY CLOSE #04-01/02 WEST STAR SINGAPORE 636996		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days