


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 09.09.2024

TO : MS FRIST CAP MOTOR CLAIMS DI
VEHICLE NO : EU8810G
MODEL : KIA CERATO FORTE
DATE OF ACCIDENT : 28.08.2024
TIME OF ACCIDENT : 12:40 HOURS

vecon

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Repair</i>	1	\$ 688.00	\$ 688.00
2	FRONT BUMPER SIDE RETAINER RH <i>new</i>	1	\$ 27.00	\$ 27.00
3	HEAD LAMP RH <i>Cut</i>	1	\$ 569.00	\$ 569.00
4	FRONT FENDER RH <i>Repair</i>	1	\$ 378.00	\$ 378.00
5	FRONT FENDER COWLING RH <i>new</i>	1	\$ 113.00	\$ 113.00
6	FRONT DOOR VIEW MIRROR RH <i>Cracked</i>	1	\$ 1,158.00	\$ 1,158.00
7	FRONT DOOR RH <i>new</i>	1	\$ 1,227.00	\$ 1,227.00
8	FRONT DOOR STICKER RH (BLACK) <i>344</i>	1	\$ 85.00	\$ 85.00
9	FRONT DOOR OUTER MOULDING RH <i>ja</i>	1	\$ 110.00	\$ 110.00
10	FRONT ABS SENSOR RH	1	\$ 245.00	\$ 245.00
11	FRONT KNUCLE ARM RH <i>Brk</i>	1	\$ 475.00	\$ 475.00
12	FRONT KNUCKLE BEARING RH <i>Brk</i>	1	\$ 256.00	\$ 256.00
13	FRONT WHEEL HUP RH <i>Brk</i>	1	\$ 240.00	\$ 240.00
14	FRONT SHOCK ABSORBER RH <i>new</i>	1	\$ 389.00	\$ 389.00
15	FRONT LOWER ARM RH <i>Brk</i>	1	\$ 436.00	\$ 436.00
16	FRONT STEERING RACK AND PINION <i>new</i>	1	\$ 1,890.00	\$ 1,890.00

TOTAL PRICE \$ 8,286.00
LESS 25% ~~10%~~ \$ 2,071.50
SUB TOTAL PRICE \$ 6,214.50

SPECIAL NETT ITEMS

TO : **MS FRIST CAP** MOTOR CLAIMS DI
 VEHICLE NO : **EU8810G**
 MODEL : **KIA CERATO FORTE**
 DATE OF ACCIDENT : 28.08.2024
 TIME OF ACCIDENT : 12:40 HOURS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER WRAPPING <i>3 per</i>	1	\$ 1,000.00	\$ 1,000.00 <i>400</i>
2	FRONT FENDER WRAPPING <i>4 per</i>	1	\$ 800.00	\$ 800.00 <i>400</i>
4	FRONT DOOR WRAPPING (SPECAIL TYPE) <i>1 per</i>	1	\$ 1,500.00	\$ 1,500.00 <i>+</i>
4	FRONT DOOR VIEW MIRROR WRAPPING <i>1 per</i>	1	\$ 380.00	\$ 380.00 <i>150</i>
6	ROCKER PANEL WRAPPING (SPECAIL TYPE) <i>1 per</i>	1	\$ 800.00	\$ 800.00 <i>+</i>
7	FRONT WHEEL RIM RH <i>1 per</i>	1	\$ 1,200.00	\$ 1,200.00 <i>400</i>
8	FRONT WHEEL TYRE RH <i>1 per</i>	1	\$ 550.00	\$ 550.00 <i>180</i>

1530

TOTAL \$ 5,680.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,000.00	<i>200</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	<i>400</i>
3	TUFF COAT	\$ 250.00	<i>30</i>
4	WIRING CHECK	\$ 80.00	<i>30</i>
5	REMOVE & REINSTALL FRONT VIEW MIRROR	\$ 60.00	<i>40</i>
6	REMOVE & REFIX STEERING RACK AND PINION	\$ 350.00	<i>+</i>
7	REMOVE & REFIX FRONT UNDER CARRIAGE	\$ 650.00	<i>200</i>
8	FOUR WHEEL ALIGNMNET	\$ 80.00	<i>✓</i>

TO : **MS FRIST CAP** MOTOR CLAIMS DI
VEHICLE NO : **EU8810G**
MODEL : **KIA CERATO FORTE**
DATE OF ACCIDENT : 28.08.2024
TIME OF ACCIDENT : 12:40 HOURS

9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
---	--	-----------	---

980

TOTAL \$ **3,650.00**

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,894.50
TOTAL LABOUR COST : \$ 3,650.00
TOTAL REPAIR COST : \$ 15,544.50

Adrian Lj
L/S 10/09/24
04 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Total: 5066.80
L/S : 4050 ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: