



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)	Ref:	CS/SPF24090171/Anp3e2
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)	Date:	23/10/2024
POLICE LOGISTICS BASE (PLB)	Code:	SPF
1 HEMMANT ROAD SINGAPORE 438675		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 213A	Veh. Inspected	SMR 5701D
Policy No.	-	Coverage	0
Claim No.	ACS/105/009/2024/045(CF)	Excess	\$0.00
Assign From	LAI PENGCHONG	Assign Date	09/09/2024

2. Vehicle Details

Make & Model	HONDA FIT	C.C	1317
Engine No.	L13B3938152	Year of Reg.	14/01/2020
Chassis No.	GK33423661	Colour	GREY
Odometer	92879 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/55 R16	MICHELIN	6
L/H Front Tyre	185/55 R16	MICHELIN	6
R/H Rear Tyre	185/55 R16	MICHELIN	6
L/H Rear Tyre	185/55 R16	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/09/2024	Inspection Date	10/09/2024
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days