

# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

TPSPF  
 Hui Rong  
**TAX INVOICE**

JEFFREY SEOW CHUANG HAN  
 BLK 26 TOA PAYOH EAST #07-172  
 SINGAPORE 310026

Contact : 98002913

Repair Code : CLM18259  
 Date in : 09/09/2024  
 Vehicle Num. : SMR5701D  
 Model : HONDA FIT 1.3GF CVT  
 Chassis/Eng# : GK33423661/L13B3938152

## Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>rehd</i>	1	551.70	551.70 <i>-</i>
FRONT BUMPER REINFORCEMENT <i>ren</i>	1	396.00	396.00 <i>+</i>
FRONT BUMPER RH FOGLAMP GARNISH <i>canhd</i>	1	39.40	39.40 <i>-</i>
FRONT BUMPER RH SIDE MOULDING <i>rehd</i>	1	21.00	21.00 <i>-</i>
FRONT BUMPER SIDE RETAINER L/R <i>ren</i>	2	14.50	29.00 <i>+</i>
FRONT RH HEADLAMP <i>canhd</i>	1	595.20	595.20 <i>-</i>
FRONT RH HEADLAMP LOWER BRACKET <i>canhd</i>	1	42.00	42.00 <i>-</i>
Subtotal before discount			1,674.30
Percentage discount 20%			334.86
<b>Sub-total 1</b>			1,339.44
FRONT BUMPER CLIPS - SET <i>m</i>	1	80.00	80.00 <i>30</i>
Subtotal before discount			80.00
Percentage discount 0%			0.00
<b>Sub-total 2</b>			80.00
<b>Parts-total</b>			<b>1,419.44</b>

## LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR) 80.00 *30*

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident. 400.00 *200*

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. 400.00 *200*

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

JEFFREY SEOW CHUANG HAN  
 BLK 26 TOA PAYOH EAST #07-172  
 SINGAPORE 310026

Contact : 98002913

**TAX INVOICE**

Repair Code : CLM18259  
 Date in : 09/09/2024  
 Vehicle Num. : SMR5701D  
 Model : HONDA FIT 1.3GF CVT  
 Chassis/Eng# : GK33423661/L13B3938152

To apply anti-rust chemical on repaired and replaced panel.

60.00

Labour Total

430

940.00

Parts & Labour Total

2,359.44

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 2

Admin G  
 2/s 10/09/24

03 Days

Total: 1459.44

4/s: 1.1K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: